國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Test Results							
Nat	Tonai ising nua university wat	El Qualli 大腸桿菌群	Ly IESL I 採樣日期	他SultS 檢測結果			
編號	受驗地點 check location	colonic	sampling	detection			
Number	Z W. C. Z enson lesseren	microbiota	date	results			
一、校石	一、校本部 Main Campus						
	行政大樓 1F大廳						
1	1st Floor Lobby of the Administrative Building	<1					
	行政大樓 1F出納組旁						
2	Administrative Building 1F Next to the cashier's	<1					
_	office						
	行政大樓 3F學長室旁(右)	<1					
3	Administrative Building 3F, next to the seniors'						
	room (right)						
4	綜四館教務處 2F廁所旁(左)	<1					
	Next to the restroom on 2F, Academic Affairs						
	Office, Zhong 4 Building (left) 工程一館動機系 401						
5	上程一態 動機系 401 Department of Mechanical Engineering, Room	<1					
	401, Engineering Building 1	\1					
6	科儀中心 1F Scientific Instrument Center 1F	<1					
7	化學館 3F Chemistry Building 3F	<1					
8	莊敬樓 1F Chuang Ching Building 1F	<1					
9	男單 1F Men's Singles Building 1F	<1					
10	清華會館 4F Guest House 4F	<1					
11	清華會館 7F Guest House 7F	<1					
12	工程四館 102A Engineering Building 4 room 10						
13	生科一館 213 Life Science Building 1 room 213	<1					
14	台積館 5F廁所旁	<1	111/02/23	符合規定 in compliance			
	Next to the toilet on 5F of TSMC Building						
				with regulations			
15	清華實驗室 3F茶水間	<1		regulations			
	Tsinghua Laboratory 3F Tea Room						
16	清華實驗室 5F茶水間	<1					
	Tsinghua Laboratory 5F Tea Room						
17	禮齋 4F 402 Li Zhai Building 4F 402	<1					
18	禮齋 4F 419 Li Zhai Building 4F 419	<1					
19	新齋 5F A區 Hsinzhai Building 5F Area A	<1					
20	新齋 B501旁 Next to Xinzhai Building B501	<1					
21	碩齋 3F 320 Shuozai Building 3F 320	<1					
22	碩齋 3F 336 Shuozai Building 3F 336	<1					
	不所 JI JJO BHUOZUI DUHUHIZ JI JJO	\1	I				

清齋D棟 4F洗衣間 Chingzhai Building D 4F Laundry Room	<1					
18889						
25 清齋D棟 5F洗衣間 Chingzhai Building D 5F Laundry Room	<1					
26 清齋D棟 8F洗衣間 Chingzhai Building D 8F Laundry Room	<1					
以下空白Blank below						
二、南大校區 NTU campus						
上 上 上 上 上 上 上 上 上 上 上 上 上 上 上 上 上 上 上	<1	111/02/23	符合規定 in compliance with regulations			
迎曦軒4F-後棟樓梯旁 2 Yingxixuan 4F-next to the stairs in the back building	<1					
樹德樓5F-512室旁 Next to Room 512 on the 5th Floor of Shude Building	<1					
樹德樓2F-洗衣機旁 4 Next to the Washing Machines on the 2nd Floor of Shude Building	<1					
以下空白Blank below						

註1.飲用水水質標準

Note 1. Drinking water quality standards.

大腸桿菌群colonic microbiota:6 (CFU/100mL)