國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Test Results Table							
Natio	mai ising mua university wate						
編號 Number	受驗地點 check location	大腸桿菌群 colonic	採樣日期 sampling	檢測結果 detection			
		microbiota		results			
一、校本	一、校本部 Main Campus						
1	綜二館天文所 5F茶水間 5F Tea Room, Astronomy Institute, Zhong 2 Building	<1					
2	校友體育館 1F茶水間 Alumni Stadium 1F Tea Room	<1					
3	台達館材料系 B1靠籃球場廁所旁 Delta Building Materials Department B1, next to the basketball court and toilets	<1					
4	台達館資工系 1F茶水間 Delta Building Salary Department 1F Tea Room	<1					
5	台達館電機系 217 Delta Building Electrical Engineering Department 217	<1					
6	台達館電機系 518 Delta Building Electrical Engineering Department 518	<1					
7	台達館資工系 7F茶水間 Delta Building Salary Department 7F Tea Room	<1					
8	台達館電機系 9F靠窗戶邊 Delta Building, Electrical Department, 9F, by the window	<1					
9	清華會館 5F Guest house 5F	<1					
10	化工館 721 Chemical Industry Building 721	<1		符合規定			
11	動化館 305 Animal and Chemical Building 305	<1	111/05/11	in compliance with			
12	駐警隊 1F Campus Security office 1F	<1		regulations			
13	綠能大樓 3F茶水間 Green Energy Building 3F Tea Room	<1					
14	台積館 6F茶水間 TSMC Building 6F Tea Room	<1					
15	清華實驗室 6F茶水間 Tsinghua Laboratory 6F Tea Room	<1					

			•	_
16	儒齋 A棟 1F Ru Zhai Building A 1F	<1		
17	儒齋 C棟 1F Ru Zhai Building C 1F	<1		
18	信齋 B棟 2F浴室 Shinn zhai Building B 2F Bathroom	<1		
19	信齋 B棟 4F浴室 Shinn zhai Building B 4F Bathroom	<1		
20	信齋 B棟 5F浴室 Shinn zhai Building B 5F Bathroom	<1		
21	信齋 A棟 1F浴室 Shinn zhai Building A 1F Bathroom	<1		
22	信齋 A棟 4F浴室 Shinn zhai Building A 4F Bathroom	<1		
23	信齋 A棟 5F浴室 Shinn zhai Building A 5F Bathroom	<1		
24	仁齋 4F 401旁 Ruzhai 4F next to 401	<1		
25	仁齋 4F 412旁 Ruzhai 4F next to 412	<1		
	以下空白 Blank below			
二、南大	大校區 NTU campus			
1	行政大樓1F-總務處茶水間 Administrative Building 1F-General Affairs Office Pantry	<1		
2	數理教育大樓4F-右側樓梯間 Mathematics and Physics Education Building 4F-stairwell on the right	<1	111/05/11	符合規定 in compliance with regulations
3	推廣教育大樓1F-前端洗手間旁 Extension Education Building 1F-next to the front restroom	<1		
4	推廣教育大樓4F-9431室(台語所辦公室) Room 4F-9431, Extension Education Building (Taiwanese Language Institute	<1		
	以下空白 Blank below			

註1.飲用水水質標準

Note 1. Drinking water quality standards.

大腸桿菌群colonic microbiota:6 (CFU/100mL)