

國立清華大學水質檢驗結果一覽表

National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	行政大樓 1F人事室旁 Administrative Building 1F Next to the Personnel Room	<1	111/03/09	符合規定 in compliance with regulations
2	行政大樓 2F第一會議室 Administrative Building 2F First Conference Room	<1		
3	行政大樓 4F營繕組 Administrative Building 4F Maintenance Team	<1		
4	綜二館 8F會議廳 8F Conference Hall, Zhong 2 Building	<1		
5	綜四館教務處 2F廁所旁(右) Next to the restroom on 2F, Academic Affairs Office, Zhong4 Building (right)	<1		
6	諮商中心 2F Counseling Center 2F	<1		
7	工程一館動機系 429 Department of Mechanical Engineering, Room 429, Engineering Building 1	<1		
8	工程一館動機系 601 Department of Mechanical Engineering, Room 601, Engineering Building 1	<1		
9	科儀中心 3F Scientific Instrument Center 3F	<1		
10	化學館 2F Chemistry Building 2F	<1		
11	動化館 1F Animation Building 1F	<1		
12	男單 2F Men's Singles Building 2F	<1		
13	自強樓 2F Ziqiang Building 2F	<1		
14	化工館 321 Chemical Industry Museum 321	<1		
15	資電館資工系 435 Department of Information and Electronics Engineering 435	<1		
16	清華實驗室 4F茶水間 Tsinghua Laboratory 4F Tea Room	<1		

17	新齋 1F洗衣間旁 Next to laundry room on 1F, Xinzhai	<1		
18	新齋 1F管理員室旁 Next to the administrator's room on Shinjai 1F	<1		
19	學C齋 1F Xue C Zhai 1F	<1		
20	鴻齋 6F洗衣間 Hungzhai 6F laundry room	<1		
21	鴻齋 2F洗衣間 Hungzhai 2F laundry room	<1		
22	鴻齋 1F洗衣間 Hungzhai 1F laundry room	<1		
23	儒B齋 2F Ru B Zhai 2F	<1		
24	儒B齋 1F Ru B Zhai 1F	<1		
25	雅齋 B1 Yazhai B1	<1		
26	文齋 2F 218 Wenzhai 2F 218	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	崇善樓5F-洗手間旁 5F, Chongshan Building - Next to the restroom	<1	111/03/09	符合規定 in compliance with regulations
2	樹德樓1F-108室旁 Next to room 108, 1F, Shude Building	<1		
3	樹德樓3F-洗衣機旁 Shude Building 3F-Next to the washing machine	<1		
4	菊月齋-1F JU-YUE 1F	<1		
	以下空白 Blank below			
<p>註1.飲用水水質標準 Note 1. Drinking water quality standards. 大腸桿菌群colonic microbiota : 6 (CFU/100mL)</p>				