

國立清華大學水質檢驗結果一覽表

National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	綜二館教務處 1F茶水間 1F Tea Room, Academic Affairs Office, Zhong 2 Building	<1	111/04/13	符合規定 in compliance with regulations
2	綜二館天文所 5F茶水間 5F Tea Room, Astronomy Institute, Zhong 2 Building	<1		
3	物理館 7F Physics Building 7F	<1		
4	綜三館理學院 4F辦公室 Office 4F, School of Science, Zhong 3 Building	<1		
5	衛保組 1F Health Security Team 1F	<1		
6	諮商中心 1F樓梯口 Consultation Center 1F stairway	<1		
7	化學館 5F Chemistry Building 5F	<1		
8	綠能大樓 1F茶水間 Green Energy Building 1F Tea Room	<1		
9	綠能大樓 5F茶水間 Green Energy Building 5F Tea Room	<1		
10	台積館 5F茶水間 TSMC Building 5F Tea Room	<1		
11	育成中心 1F Incubation Center 1F	<1		
12	育成中心 4F Incubation Center 4F	<1		
13	清華實驗室 2F茶水間 Tsinghua Laboratory 2F Tea Room	<1		
14	清華實驗室 7F茶水間 Tsinghua Laboratory 7F Tea Room	<1		
15	信C齋 4F浴室 Shinn C Zhai 4F bathroom	<1		
16	信C齋 5F浴室 Shinn C Zhai 5F bathroom	<1		
17	仁齋 3F 301旁 Jenzhai 3F next to 301	<1		
18	仁齋 3F 312旁 Jenzhai 3F next to 312	<1		
19	義齋 3F 301旁 Yihai 3F next to 301	<1		

20	義齋 3F 317旁 Yihai 3F next to 317	<1		
21	清齋 D棟7F洗衣間 Laundry Room 7F, Building D, Chingzhai	<1		
22	清齋 AB棟電梯前 In front of the elevator in Building AB, Chingzhai	<1		
23	鴻齋 8F洗衣間 Hungzhai 8F laundry room	<1		
24	鴻齋 7F洗衣間 Hungzhai 7F laundry room	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	樹德樓1F-洗衣機旁 Shude Building 1F-Next to the washing machine	<1	111/04/13	符合規定 in compliance with regulations
2	樹德樓4F-洗衣機旁 Shude Building 4F-Next to the washing machine	<1		
3	樹德樓5F-洗衣機旁 Shude Building 5F-Next to the washing machine	<1		
4	樹德樓1F-男宿入口處 Shude Building 1F- Entrance to Men's Dormitory	<1		
	以下空白 Blank below			
<p>註1.飲用水水質標準 Note 1. Drinking water quality standards. 大腸桿菌群colonic microbiota : 6 (CFU/100mL)</p>				