

國立清華大學水質檢驗結果一覽表

National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	駐警隊 南門收費亭 Campus Security office South Gate Toll Booth	<1	111/07/06	符合規定 in compliance with regulations
2	台積館 1F廁所旁 Next to the toilet on 1F of TSMC Building	<1		
3	育成中心 6F Incubation Center 6F	<1		
4	工科館 402E旁 Next to Engineering Building 402E	<1		
5	工科新館 4F Engineering New Building 4F	<1		
6	綠能大樓 4F Green Energy Building 4F	<1		
7	綜二館學科所 4F教授休息室 Professor's Lounge 4F, Institute of Science, Second Building	<1		
8	物理館 4F Physics Building 4F	<1		
9	化工館 1F閱覽室 Chemical Industry Building 1F Reading Room	<1		
10	台達館材料系 B12對面 Department of Materials, Delta Building opposite B12	<1		
11	台達館電機系 203旁 Next to Room 203, Department of Electrical Engineering, Delta Building	<1		
12	台達館材料系 432 Department of Materials, Delta Building 432	<1		
13	台達館電機系 936 Delta Building Electrical Engineering Department 936	<1		
14	清華會館 6F Guest house 6F	<1		
15	保管組 女單1F Storage Team Women's Singles 1F	<1		
16	學A齋 6F Shiue A Zhai 6F	<1		
17	學A齋 7F Shiue A Zhai 7F	<1		
18	儒A齋 6F Ru A Zhai 6F	<1		

19	儒A齋 5F Ru A Zhai 5F	<1		
20	儒B齋 3F Ru B Zhai 3F	<1		
21	碩齋 5F 502 Shuozhai 5F 502	<1		
22	碩齋 5F 520 Shuozhai 5F 520	<1		
23	碩齋 5F 536 Shuozhai 5F 536	<1		
24	碩齋 3F 302 Shuozhai 3F 302	<1		
25	碩齋 2F 236 Shuozhai 2F 236	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	行政大樓2F-系聯合辦公室 Administrative Building 2F-Department Joint Office	<1	111/07/06	符合規定 in compliance with regulations
2	舊圖書館2F-辦公室走廊 Old Library 2F-Office Corridor	<1		
3	飲虹樓1F-教職員宿舍 1F, Yinhong Building-teachers' dormitory	<1		
4	學生活動中心3F-洗手間旁 Student Activity Center 3F-Next to the restroom	<1		
	以下空白 Blank below			
<p>註1.飲用水水質標準 Note 1. Drinking water quality standards. 大腸桿菌群colonic microbiota : 6 (CFU/100mL)</p>				