

國立清華大學水質檢驗結果一覽表

National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	台達館資工系 105 Delta Building Salary Department 105	<1	111/08/03	符合規定 in compliance with regulations
2	台達館電機系 218 Delta Building Electrical Engineering Department 218	<1		
3	台達館材料系 4F茶水間 Delta Building Materials Department 4F Tea Room	<1		
4	台達館電資院 303 Delta Building Electric Power Equipment Institute 303	<1		
5	台達館電資院 5F茶水間 Delta Building Electric Power Equipment Institute 5F Tea Room	<1		
6	台達館電機系 8F茶水間 Delta Building Electrical Engineering Department 8F Tea Room	<1		
7	工程四館 501 Engineering Building 4 501	<1		
8	清華實驗室 9F茶水間 Tsinghua Laboratory 9F Tea Room	<1		
9	清齋B棟 1F洗衣間 Chingzhai Building B 1F Laundry Room	<1		
10	清齋B棟 3F洗衣間 Chingzhai Building B 3F Laundry Room	<1		
11	清齋AB棟 10F電梯前 In front of the elevator on 10F, Building AB, Chingzhai	<1		
12	清齋DE棟 8F電梯前 In front of the elevator on 8F, Building DE, Chingzhai	<1		
13	學齋B棟 3F Shiue B Zhai 3F	<1		
14	學齋B棟 4F Shiue B Zhai 4F	<1		

15	學齋B棟 5F Shiue B Zhai 5F	<1		
16	儒齋A棟 2F Ru zhai Building A 2F	<1		
17	儒齋A棟 3F Ru zhai Building A 3F	<1		
18	儒齋A棟 4F Ru zhai Building A 4F	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	新圖書館1F-休閒閱覽室 New Library 1F-Leisure Reading Room	<1	111/08/03	符合規定 in compliance with regulations
2	綜合教學大樓B1-國際會議廳 Comprehensive Teaching Building B1- International Conference Hall	<1		
3	綜合教學大樓2F-210室旁 Next to Room 210, 2F-210, Comprehensive Teaching Building	<1		
4	綜合教學大樓8F-茶水間 Comprehensive teaching building 8F-pantry	<1		
	以下空白 Blank below			
<p>註1.飲用水水質標準 Note 1. Drinking water quality standards.</p> <p style="text-align: center;">大腸桿菌群colonic microbiota : 6 (CFU/100mL)</p>				