

國立清華大學水質檢驗結果一覽表

National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	蒙民偉樓 1F Mong Man Wai Building 1F	<1	111/09/07	符合規定 in compliance with regulations
2	名人堂 2F Hall of Fame 2F	<1		
3	台達館材料系 B1廁所旁 Department of Materials, Delta Building, next to toilet B1	<1		
4	台達館材料系 4F茶水間 Delta Building Materials Department 4F Tea Room	<1		
5	台達館資工系 6F靠籃球窗戶 Delta Building Payroll Department 6F next to the basketball window	<1		
6	台達館電機系 8F靠籃球窗戶 Delta Building, Electrical Department, 8F, next to the basketball window	<1		
7	台達館電機系 913 Delta Building Electrical Engineering Department 913	<1		
8	工科館 3F茶水間 Engineering Building 3F Tea Room	<1		
9	生科一館 413 Life Science Building 1 room 413	<1		
10	生科二館 535 Life Science Building 2 room 535	<1		
11	人社院 A312 Humanity&Social Science Building A312	<1		
12	人社院 B406 Humanity&Social Science Building B406	<1		
13	人社院 A619 Humanity&Social Science Building A619	<1		
14	育成中心 8F Incubation Center 8F	<1		
15	學齋 B棟6F Shiue Zhai Building B 6F	<1		
16	學齋 B棟7F Shiue Zhai Building B 7F	<1		
17	學齋 C棟2F Shiue Zhai Building C 2F	<1		
18	學齋 C棟3F Shiue Zhai Building C 3F	<1		

19	學齋 D棟1F Shiue Zhai Building D 1F	<1		
20	儒齋 B棟4F Ru Zhai Building B 4F	<1		
21	儒齋 A棟7F Ru Zhai Building A 7F	<1		
22	靜齋 2F 207 Jingzhai 2F 207	<1		
23	靜齋 2F 208 Jingzhai 2F 208	<1		
24	慧齋 1F廚房 Hueizhai 1F Kitchen	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	行政大樓5F-右側洗手間旁 Administration Building 5F-Next to the restroom on the right	<1	111/09/07	符合規定 in compliance with regulations
2	新圖書館5F-電梯旁 New Library-5F-next to the elevator	<1		
3	綜合教學大樓2F-後端茶水間 Comprehensive Teaching Building 2F-Back-end Pantry	<1		
4	綜合教學大樓3F-後端茶水間 Comprehensive Teaching Building 3F-Back-end Pantry	<1		
	以下空白 Blank below			
<p>註1.飲用水水質標準 Note 1. Drinking water quality standards.</p> <p style="text-align: center;">大腸桿菌群colonic microbiota : 6 (CFU/100mL)</p>				