

國立清華大學水質檢驗結果一覽表

National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	計算機中心 211 Computer Center 211	<1	111/10/05	符合規定 in compliance with regulations
2	綜三館數學系 100 Department of Mathematics 100, Zhong 3 Building	<1		
3	蒙民偉樓 3F Mong Man Wai Building 3F	<1		
4	台達館電機系 2F茶水間 Delta Building Electrical Engineering Department 2F Tea Room	<1		
5	台達館奈微所 323 Delta Building Naiwei Institute 323	<1		
6	台達館材料系 410 Delta Building Materials Department 410	<1		
7	台達館資工系 7F靠籃球場 Delta Building Payroll Department 7F next to the basketball court	<1		
8	台達館電機系 853 Delta Building Electrical Engineering Department 853	<1		
9	工程四館 202 Engineering Building 4 202	<1		
10	工程一館動機系 501 Department of Mechanical Engineering, Room 501, Engineering Building 1	<1		
11	生物科技館 2F走廊 Biotechnology Building 2F Corridor	<1		
12	人社院 C416 Humanity&Social Science Building C416	<1		
13	人社院 C633 Humanity&Social Science Building C633	<1		
14	新齋 A棟7F洗衣機旁 Next to the washing machine on 7F, Building A, Hsinzhai	<1		

15	儒齋 A棟2F交誼廳 2F Social Hall, Building A, Ruzhai	<1		
16	鴻齋 1F洗衣間 Hongzhai 1F Laundry Room	<1		
17	雅齋 4F 410 Yazhai 4F 410	<1		
18	雅齋 4F 425 Yazhai 4F 425	<1		
19	文齋 1F 102 Wenzhai 1F 102	<1		
20	文齋 2F 202 Wenzhai 2F 202	<1		
21	文齋 2F 218 Wenzhai 2F 218	<1		
22	明齋 1F浴室 Mingzhai 1F bathroom	<1		
23	平齋 1F浴室 Pingzhai 1F bathroom	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	綜合教學大樓5F-後端茶水間 Comprehensive Teaching Building 5F-Back-end Pantry	<1	111/10/05	符合規定 in compliance with regulations
2	教學大樓1F-2105室 Room 1F-2105, Teaching Building	<1		
3	學生活動中心4F-洗手間旁 Student Activity Center 4F-next to the restroom	<1		
4	體健大樓4F-405室旁 Physical Fitness Building 4F-Next to Room 405	<1		
	以下空白 Blank below			
<p>註1.飲用水水質標準 Note 1. Drinking water quality standards. 大腸桿菌群colonic microbiota：6 (CFU/100mL)</p>				