

國立清華大學水質檢驗結果一覽表

National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌 群 colonic microbiot	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	行政大樓 168教室 Classroom 168, Administration Building	<1	111/12/14	符合規定 in compliance with regulations
2	行政大樓 3F校規組對面左 Administrative Building 3F opposite the Campus Planning Group on the left	<1		
3	行政大樓 3F學務長室旁左 Administrative Building 3F, next to the Dean's Office, left	<1		
4	化工館 112 Chemical Industry Building 112	<1		
5	綜二館電子所 3F廁所旁 Next to the restroom on the 3F of the Zhong 2 Building Electronics Department	<1		
6	綜二館 1F教授休息室 Professor's Lounge on 1F, Zhong 2 Building	<1		
7	蒙民偉樓 5F Mong Man Wai Building 5F	<1		
8	名人堂 1F Hall of Fame 1F	<1		
9	水木生活中心 2F Shui Mu Student Center 2F	<1		
10	風雲樓 2F Fengyun Building 2F	<1		
11	學人宿舍 1F Scholar's Dormitory 1F	<1		
12	資電館資工系 220 Department of Information and Electronics Engineering Building 220	<1		
13	台達館電機系 813 Delta Building Electrical Engineering Department 813	<1		
14	台達館電機系 9F茶水間 Delta Building Electrical Engineering Department 9F Tea Room	<1		
15	工科館 421教授休息室 Engineering Building 421 Professor Lounge	<1		
16	生物科技館 116 Biotechnology Building 116	<1		
17	生科一館 315 Life Science Building 1 room 315	<1		
18	生科二館 313 Life Science Building 2 room 313	<1		
19	人社院 A523 Humanity&Social Science Building A523	<1		

20	人社院 C507 Humanity&Social Science Building C507	<1		
21	育成中心學士後醫系 3F茶水間 3F Tea Room, Department of Postgraduate Medicine, Incubation Center	<1		
22	雅齋 3F 310 Yazhai 3F310	<1		
23	雅齋 3F 328 Yazhai 3F 328	<1		
24	儒齋 B棟5F Ru Zhai Building B 5F	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	行政大樓2F-茶水間 Administrative Building 2F - Pantry	<1	111/12/14	符合規定 in compliance with regulations
2	行政大樓4F-右側洗手間旁 Administrative Building 4F-Next to the restroom on the right	<1		
3	警衛室1F-土銀提款機旁 1st Floor Security Office, Next to the Land Bank ATM	<1		
4	綜合教學大樓9F-茶水間(招待所) Comprehensive Teaching Building 9F - Tea Room (Guest House)	<1		
5	藝設系大樓4F-電梯邊 4F, Department of Art and Design Building - Elevator side	<1		
6	資源回收場 Resource recovery site	<1		
7	體健大樓-4F-廁所旁 Physical Fitness Building-4F-next to the toilet	<1		
8	推廣教育大樓2F-9213室 Extension Education Building 2F-Room 9213	<1		
9	推廣教育大樓3F-電梯旁 Extension Education Building-3F-next to the elevator	<1		
10	推廣教育大樓4F-9412室(數理所辦公室) Room 4F-9412, Extension Education Building (Institute of Mathematics and Physics Office)	<1		
11	竹師攬星樓-1F-(校外宿舍) Zhushi Lanxing Building-1F-(off-campus dormitory)	<1		
12	鳴鳳樓-2F-洗手間旁(力霸) Mingfeng Building-2F-Next to the restroom (Liba)	<1		
13	迎曦軒-3F-後棟樓梯旁(力霸) Yingxixuan-3F-Next to the stairs in the back building (Liba)	<1		
	以下空白 Blank below			
註1.飲用水水質標準 Note 1. Drinking water quality standards. 大腸桿菌群colonic microbiota : 6 (CFU/100mL)				