

國立清華大學水質檢驗結果一覽表

National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	碩齋 1F 102旁 Shuo Zhai 1F next to 102	<1	112/02/08	符合規定 in compliance with regulations
2	信A齋 3F浴室 Shinn A Zhai 3F bathroom	<1		
3	信B齋 1F浴室 Shinn B Zhai 1F bathroom	<1		
4	信C齋 1F浴室 Shinn C Zhai 1F bathroom	<1		
5	學D齋 3F Xue D Zhai 3F	<1		
6	儒B齋 6F Ru B Zhai 6F	<1		
7	清D齋 5F洗衣間 Ching D Zhai 5F laundry room	<1		
8	文齋 302(3F) Wen Zhai 302(3F)	<1		
9	靜齋 1F洗手間旁 JingZhai 1F next to the restroom	<1		
10	醫環館 304 Department of Biomedical Engineering and Environmental Sciences 304	<1		
11	綠能大樓 6F茶水間 Green Energy Building 6F Tea Room	<1		
12	台積館 8F廁所旁 Next to the restroom on 8F, TSMC Building	<1		
13	人社院 C205 Humanity&Social Science Building C205	<1		
14	台積館 4F茶水間 TSMC Building 4F Tea Room	<1		
15	台積館 1F茶水間 TSMC Building 1F Tea Room	<1		
16	育成中心 7F Incubation Center 7F	<1		
17	工科新館 2F New Engineering Building 2F	<1		
18	第二招待所 3F The second guest house 3F	<1		
19	教育館 1F茶水間 Education Building 1F Tea Room	<1		
20	圖書館 1F公務區茶水間 Library 1F official area tea room	<1		
21	化工館 B1 Chemical Industry Building B1	<1		
22	駕駛班 茶水間 Driving School tea room	<1		
23	化學館 112教授休息室 Chemistry Hall 112 Professor Lounge	<1		

24	綜二館教務處 6F茶水間 Tea Room 6F, Academic Affairs Office, Zhong 2 Building	<1		
25	外工班 走廊 Outdoor Work Crew corridor	<1		
26	教育館 214 Education Building room 214	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	行政大樓1F-茶水間 Administrative Building 1F - tea room	<1	112/02/08	符合規定 in compliance with regulations
2	綜合教學大樓4F-前端茶水間 Comprehensive teaching building 4F-front tea room	<1		
3	教學大樓-3F-2304室旁 Teaching Building-3F-Next to Room 2304	<1		
4	鳴鳳樓3F-洗手間旁 Mingfeng Building 3F-Next to the restroom	<1		
5	崇善樓-3F-洗手間旁(力霸) Next to the restroom on 3F, Chongshan Building (Liba)	<1		
	以下空白 Blank below			
<p>註1.飲用水水質標準 Note 1. Drinking water quality standards. 大腸桿菌群colonic microbiota : 6 (CFU/100mL)</p>				