

國立清華大學水質檢驗結果一覽表

National Tsing Hua University Water Quality Test Results Table

| 編號 Number | 受驗地點 check location | 大腸桿菌群 colonic microbiota | 採樣日期 sampling date | 檢測結果 detection results |
|-------------------|---------------------------------------------------------------------------------------|--------------------------------|--------------------------|-------------------------------------------------|
| 一、校本部 Main Campus | | | | |
| 1 | 圖書館 1F讀者區廁所旁 Library 1F reader area next to toilet | <1 | 112/03/08 | 符合規定 in compliance with regulations |
| 2 | 圖書館 5F讀者區廁所旁 Library 5F reader area next to toilet | <1 | | |
| 3 | 旺宏館 729 Wang Hong Building 729 | <1 | | |
| 4 | 綜三館統計所 8F教授休息室 Professor's Lounge 8F, Institute of Statistics, Zhong 3 Building | <1 | | |
| 5 | 綜二館資工系 710 Department of Information Engineering, Zhong 2 Building 710 | <1 | | |
| 6 | 綜二館技科所 8F茶水間 8F Tea Room, Institute of Technology, Zhong 2 Building | <1 | | |
| 7 | 綜二館計算機中心 415 Computer Center of Zhong 2 Building 415 | <1 | | |
| 8 | 台達館資工系 520 Delta Building Electrical Engineering Department 520 | <1 | | |
| 9 | 醫環館 604 Department of Biomedical Engineering and Environmental Sciences 604 | <1 | | |
| 10 | 工科新館 1F New Engineering Building 1F | <1 | | |
| 11 | 工科新館 5F New Engineering Building 5F | <1 | | |
| 12 | 人社院劇場 D104 Humanity&Social Science Building Theater, Room D104 | <1 | | |
| 13 | 人社院 C307 Humanity&Social Science Building C307 | <1 | | |
| 14 | 人社院圖書館 2F Humanity&Social Science Building Library, Room D104 | <1 | | |
| 15 | 生科二館 412 Life Science Building 2 room 412 | <1 | | |
| 16 | 台積館 2F廁所旁 Next to the restroom on 2F, TSMC Building | <1 | | |
| 17 | 學齋 D棟4F Shiue Zhai Building D 4F | <1 | | |
| 18 | 儒齋 B棟7F Ru Zhai Building B 7F | <1 | | |

| | | | | |
|-----------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|----|-----------|-------------------------------------------------|
| 19 | 儒齋 C棟3F Ru Zhai Building C 3F | <1 | | |
| 20 | 儒齋 C棟4F Ru Zhai Building C 4F | <1 | | |
| 21 | 儒齋 C棟6F Ru Zhai Building C 6F | <1 | | |
| 22 | 儒齋 D棟5F Ru Zhai Building D 5F | <1 | | |
| 23 | 儒齋 D棟4F Ru Zhai Building D 4F | <1 | | |
| 24 | 清齋 D棟8F洗衣間 Ching Zhai Building D 8F Laundry Room | <1 | | |
| 25 | 清齋 DE棟5F電梯前 In front of the elevator on 5F, Building DE, Ching Zhai | <1 | | |
| 26 | 清齋 AB棟7F電梯前 In front of the elevator on 7F, Building AB, Ching Zhai | <1 | | |
| | 以下空白 Blank below | | | |
| 二、南大校區 NTU campus | | | | |
| 1 | 學生活動中心2F-茶水間 Student Activity Center 2F - Tea room | <1 | 112/03/08 | 符合規定 in compliance with regulations |
| 2 | 體育館-1F Gym-1F | <1 | | |
| 3 | 學生第二活動中心-2F Student Activity Center 2F | <1 | | |
| 4 | 音樂館-1F-走廊 Music Building 1F-Corridor | <1 | | |
| 5 | 崇善樓4F-洗手間旁(力霸) Next to the restroom on 4F, Chongshan Building (Liba) | <1 | | |
| | 以下空白 Blank below | | | |
| <p>註1.飲用水水質標準 Note 1. Drinking water quality standards. 大腸桿菌群colonic microbiota：6 (CFU/100mL)</p> | | | | |