

國立清華大學水質檢驗結果一覽表

National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	圖書館 3F 讀者區廁所旁 Library 3F reader area next to toilet	<1	112/04/12	符合規定 in compliance with regulations
2	圖書館 5F 讀者區茶水間 Library 5F reader area next to toilet	<1		
3	教育館 217 Educational Building room 217	<1		
4	綜三館數學系 302 Department of Mathematics, Zhong 3 Building 302	<1		
5	綜三館普物教室 201 Physics Classroom 201, Zhong 3 Building	<1		
6	綜二館資工系 743 Department of Information Engineering, Zhong 2 Building 743	<1		
7	綜二館教務處 6F 茶水間 Tea Room 6F, Academic Affairs Office, Zhong 2 Building	<1		
8	綜二館學科所 4F 茶水間 4F Tea Room, Academic Institute, Zhong 2 Building	<1		
9	物理館 5F Physics Building 5F	<1		
10	資電館資工系 531 Department of Information and Electronics Engineering 531	<1		
11	校友體育館 2F Alumni Gym 2F	<1		
12	工程三館 108 Engineering Building 3 108	<1		
13	工程四館 301 Engineering Building 4 301	<1		
14	工科館 5F 茶水間 Engineering Building 5F Tea Room	<1		
15	台積館 3F 茶水間 TSMC Building 1F Tea Room	<1		
16	綜四館經管組 201(左) Economics and Management Section 201 of Zhong 4 Building(left)	<1		
17	誠齋 1F 樓梯東 Chengzhai 1F Staircase East	<1		
18	實齋 1F 浴室 Shyrzhai 1F bathroom	<1		

19	實齋 1F交誼廳 Shyrzhai 1F Social Hall	<1		
20	清齋 AB棟8F電梯前 In front of the elevator on 8F, Building AB, Ching Zhai	<1		
21	清齋 AB棟1F流理台旁 Next to the sink on the 1F, Building AB, Ching Zhai	<1		
22	清齋 DE棟10F電梯前 In front of the elevator on 10F, Building DE, Ching Zhai	<1		
23	清齋 D棟9F洗衣間 Ching Zhai Building D 9F Laundry Room	<1		
24	儒齋 C棟7F Ru Zhai Building C 7F	<1		
25	儒齋 C棟5F Ru Zhai Building C 5F	<1		
26	儒齋 D棟6F Ru Zhai Building D 6F	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	體健大樓5F-504室旁 Physical Fitness Building 5F-Next to Room 504	<1	112/04/12	符合規定 in compliance with regulations
2	推廣教育大樓5F-前端洗手間旁 Extension Education Building 5F-next to the front restroom	<1		
3	迎曦軒1F-後棟樓梯旁(力霸) Yingxixuan 1F-next to the stairs in the back building (Liba)	<1		
4	樹德樓2F-212室旁(力霸) Shude Building 2F-Next to Room 212 (Liba)	<1		
5	樹德樓-3F-312室旁(力霸) Shude Building 3F-Next to Room 312 (Liba)	<1		
	以下空白 Blank below			
<p>註1.飲用水水質標準 Note 1. Drinking water quality standards.</p> <p>大腸桿菌群colonic microbiota : 6 (CFU/100mL)</p>				