

國立清華大學水質檢驗結果一覽表
National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	圖書館 2F讀者區廁所旁 Library 2F reader area next to toilet	<1	112/05/03	符合規定 in compliance with regulations
2	圖書館 3F讀者區茶水間 Library 3F reader area next to toilet	<1		
3	圖書館 4F讀者區廁所旁 Library 4F reader area next to toilet	<1		
4	旺宏館教室 2F茶水間(左) Wang Hong Building Classroom 2F tea room (left)	<1		
5	綜四館經管組 201(右) Economics and Management Team of Zhong 4 Building 201 (right)	<1		
6	綜二館計算機中心 616 Computer Center of Zhong 2 Building 616	<1		
7	綜三館數學系 701 Department of Mathematics, Zhong 3 Building 701	<1		
8	綜三館統計所 806會議室 Meeting Room 806, Department of Statistics, Zhong 3 Building	<1		
9	工程三館 209 Engineering Building 3 209	<1		
10	資電館資工系 631 Department of Information and Electronics Engineering 631	<1		
11	物理館 1F Physics Building 1F	<1		
12	水木生活中心 洗衣部旁 Shuimu Life Center Next to Laundry Department	<1		
13	工科新館 3F New Engineering Building 3F	<1		
14	生科一館 108 Life Science Building 1 room 108	<1		
15	人社院劇場 D302 Humanity&Social Science Building Theater, Room D302	<1		
16	人社院劇場 C404 Humanity&Social Science Building Theater, Room C404	<1		

17	人社院劇場 C611 Humanity&Social Science Building Theater, Room C611	<1		
18	禮齋 1F 102 Li Zhai 1F 102	<1		
19	禮齋 1F 119 Li Zhai 1F 1119	<1		
20	新齋 2F B207對面 Hsin Zhai 2F Opposite B207	<1		
21	新齋 2F B206對面 Hsin Zhai 2F Opposite B206	<1		
22	學齋 A棟1F Shiue Zhai Building A 1F	<1		
23	學齋 A棟2F Shiue Zhai Building A 2F	<1		
24	鴻齋 2F洗衣間 Hung Zhai 2F laundry room	<1		
25	儒齋 C棟2F Ru Zhai Building C 2F	<1		
26	平齋 2F浴室 Ping Zhai 2F bathroom	<1		
27	平齋 3F浴室 Ping Zhai 3F bathroom	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	行政大樓3F-右側洗手間旁 Administrative Building 3F-Next to the restroom on the right	<1	112/05/03	符合規定 in compliance with regulations
2	綜合教學大樓-4F-後端茶水間 Comprehensive Teaching Building 4F-Back-end tea room	<1		
3	藝設系大樓2F廁所邊 Next to the restroom on 2F, Department of Art and Design Building	<1		
4	音樂二館-3F Music Building 2-3F	<1		
5	迎曦軒2F-後棟樓梯旁 Yingxixuan 2F-next to the stairs in the back building	<1		
	以下空白 Blank below			
<p>註1.飲用水水質標準 Note 1. Drinking water quality standards.</p> <p style="text-align: center;">大腸桿菌群colonic microbiota : 6 (CFU/100mL)</p>				