

國立清華大學水質檢驗結果一覽表
National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	旺宏館全球處 1F茶水間 Wang Hong Building Global Office 1F tea room	<1	112/06/07	符合規定 in compliance with regulations
2	旺宏館7F校長室 茶水間 Principal's Office, Pantry, 7F, Wang Hong Building	<1		
3	圖書館 2F讀者區 茶水間 Library 2F reader area next to toilet	<1		
4	圖書館 3F公務區 Library 3F official area	<1		
5	教育館 3F靠光復中學 Educational Building 3F, Guangfu Middle School	<1		
6	綜三館數學系 610 Department of Mathematics, Zhong 3 Building 610	<1		
7	綜三館統計系 637 Department of Statistics, Zhong 3 Building 637	<1		
8	工科新館 7F New Engineering Building 7F	<1		
9	醫環系 203 Department of Biomedical Engineering and Environmental Sciences 203	<1		
10	醫環系 704 Department of Biomedical Engineering and Environmental Sciences 704	<1		
11	圖書館人社院分館 1F Library Humanities and Social Sciences Branch 1F	<1		
12	人社院 B304 Humanity&Social Science Building B304	<1		
13	台積館 4F廁所旁 Next to the restroom on 4F, TSMC Building	<1		
14	台積館 6F廁所旁 Next to the restroom on 6F, TSMC Building	<1		
15	台積館 8F茶水間 TSMC Building 8F Tea Room	<1		
16	靜齋 3F 315 Jingzhai 3F 315	<1		
17	靜齋 3F浴室外 Outside the bathroom on Jingzhai 3F	<1		
18	慧齋 1F交誼廳 Huizhai 1F Social Hall	<1		

19	學齋 A棟5F Shieuzhai Building A 5F	<1		
20	學齋 A棟4F Shieuzhai Building A 4F	<1		
21	學齋 A棟3F Shieuzhai Building A 3F	<1		
22	清齋 D棟6F洗衣間 Laundry room on 6F, Building D, chingzhai	<1		
23	清齋 AB棟電梯前 In front of the elevator in Building AB, Qingzhai	<1		
24	清齋 B棟5F洗衣間 Chingzhai Building B 5F Laundry Room	<1		
25	儒齋 D棟1F Ruzhai Building D 1F	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	綜合教學大樓1F-後端茶水間 Comprehensive Teaching Building 1F-Back-end tea room	<1	112/06/07	符合規定 in compliance with regulations
2	綜合教學大樓5F-前端茶水間 Comprehensive teaching building 5F-front tea room	<1		
3	教學大樓2F-中央樓梯間 Teaching Building-2F-Central Stairwell	<1		
4	藝設系大樓3F-樓梯邊 Department of Art and Design Building-3F-next to the stairs	<1		
5	學生活動中心1F-入口左側 Student Activity Center-1F-left side of entrance	<1		
	以下空白 Blank below			
<p>註1.飲用水水質標準 Note 1. Drinking water quality standards.</p> <p>大腸桿菌群colonic microbiota : 6 (CFU/100mL)</p>				