

國立清華大學水質檢驗結果一覽表
National Tsing Hua University Water Quality Test Results Table

| 編號 Number | 受驗地點 check location | 大腸桿菌群 colonic microbiota | 採樣日期 sampling date | 檢測結果 detection results |
|-------------------|---|--------------------------------|--------------------------|--|
| 一、校本部 Main Campus | | | | |
| 1 | 資電館資工系 730 Department of Information and Electronics Engineering 730 | <1 | 112/07/05 | 符合規定 in compliance with regulations |
| 2 | 資電館電機系 523 Department of Electrical Engineering, Information and Electronics Building 523 | <1 | | |
| 3 | 物理館 3F Physics Building 3F | <1 | | |
| 4 | 工程四館 401 Engineering Building 4 401 | <1 | | |
| 5 | 綜三館統計所 842 Department of Statistics, Zhong 3 Building 842 | <1 | | |
| 6 | 旺宏館國際會議廳 B1走廊 Wang Hong Building International Conference Hall B1 Corridor | <1 | | |
| 7 | 圖書館 4F讀者區茶水間 Library 4F reader area next to toilet | <1 | | |
| 8 | 圖書館 4F/K書中心 Library 4F/K Book Center | <1 | | |
| 9 | 圖書館 6F讀者區廁所旁 Library 6F reader area next to toilet | <1 | | |
| 10 | 風雲樓 3F Fengyun Building 3F | <1 | | |
| 11 | 台積館 9F廁所旁 Next to the restroom on 9F, TSMC Building | <1 | | |
| 12 | 育成中心 5F Incubation Center 5F | <1 | | |
| 13 | 育成中心 9F Incubation Center 9F | <1 | | |
| 14 | 誠齋 2F樓梯東 Cheng Zhai 2F Staircase East | <1 | | |
| 15 | 誠齋 2F樓梯西 Cheng Zhai 2F Staircase West | <1 | | |
| 16 | 禮齋 3F 302 Li Zhai 3F 302 | <1 | | |
| 17 | 禮齋 3F 319 Li Zhai 3F 319 | <1 | | |
| 18 | 清齋 B棟6F洗衣間 Chingzhai Building B 6F Laundry Room | <1 | | |
| 19 | 清齋 B棟8F洗衣間 Chingzhai Building B 8F Laundry Room | <1 | | |
| 20 | 清齋 B棟9F洗衣間 Chingzhai Building B 9F Laundry Room | <1 | | |
| 21 | 明齋 2F浴室 Ming Zhai 2F bathroom | <1 | | |
| 22 | 明齋 3F浴室 Ming Zhai 2F bathroom | <1 | | |

| | | | | |
|---|---|----|-----------|--|
| 23 | 實齋 3F浴室西 Shyr Zhai 3F bathroom west | <1 | | |
| | 以下空白 Blank below | | | |
| 二、南大校區 NTU campus | | | | |
| 1 | 竹師會館3F-樓梯口 Bamboo Master Building 3F-Stairway | <1 | 112/07/05 | 符合規定 in compliance with regulations |
| 2 | 綜合教學大樓6F-茶水間 Comprehensive teaching building 6F-tea room | <1 | | |
| 3 | 教學大樓1F-2105室 Room 1F 2105, Teaching Building | <1 | | |
| 4 | 飲虹樓-B1-健身有氧中心 Yinhong Building-B1-Fitness and Aerobic Center | <1 | | |
| 5 | 體育室-2F Gym-2F | <1 | | |
| | 以下空白 Blank below | | | |
| <p>註1.飲用水水質標準 Note 1. Drinking water quality standards. 大腸桿菌群colonic microbiota : 6 (CFU/100mL)</p> | | | | |