

**國立清華大學水質檢驗結果一覽表**  
National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	人社院 A420 Humanity&Social Science Building A420	<1	112/08/02	符合規定 in compliance with regulations
2	醫環館 503 Department of Biomedical Engineering and Environmental Sciences 503	<1		
3	第二招待所 5F The second guest house 5F	<1		
4	材料實驗館 1F Materials Experiment Building 1F	<1		
5	圖書館 2F公務區 Library 2F official area	<1		
6	圖書館 4F公務區 Library 4F official area	<1		
7	圖書館 6F讀者區茶水間 Library 6F reader area next to toilet	<1		
8	旺宏館國際會議廳 1F休息室 Wang Hong Building International Conference Hall 1F Lounge	<1		
9	旺宏館教室 2F茶水間(右) Wang Hong Building Classroom 2F tea room (right)	<1		
10	工程一館工學院 3F院辦公室 Office 3F, College of Engineering, Building 1	<1		
11	綜二館藝術中心 1F茶水間 Zhong 2 Building Art Center 1F Tea Room	<1		
12	新齋 7F B706對面 Hshin Zhai 7F Opposite B706	<1		
13	新齋 6F B606對面 Hshin Zhai 6F Opposite B606	<1		
14	新齋 7F A區 Hsiin Zhai 7F Area A	<1		
15	清齋 DE棟 9F電梯前 In front of the elevator on 9F, Building DE, Ching Zhai	<1		
16	清齋 DE棟 7F電梯前 In front of the elevator on 7F, Building DE, Ching Zhai	<1		

17	清齋 DE棟 6F電梯前 In front of the elevator on 6F, Building DE, Ching Zhai	<1		
18	禮齋 2F 202 Li Zhai 2F 202	<1		
19	禮齋 2F 220 Li Zhai 2F 202	<1		
20	實齋 3F浴室東 Shyr Zhai 3F Bathroom East	<1		
21	仁齋 2F 212旁 Jen Zhai 2F next to 212	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	新圖書館3F-電梯旁 New Library 3F-next to the elevator	<1	112/08/02	符合規定 in compliance with regulations
2	學生活動中心1F-衛保組 Student Activity Center 1F-Health Protection Team	<1		
3	體健大樓 5F-籃球場 Physical Fitness Building 5F-Basketball Court	<1		
4	推廣教育大樓1F-前端洗手間旁 Extension Education Building 1F-next to the front toilet	<1		
5	推廣教育大樓 4F-後端洗手間旁 Extension Education Building-4F-Next to the restroom at the back end	<1		
	以下空白 Blank below			
註1.飲用水水質標準 Note 1. Drinking water quality standards. 大腸桿菌群colonic microbiota : 6 (CFU/100mL)				