

國立清華大學水質檢驗結果一覽表
National Tsing Hua University Water Quality Test Results Table

編號 Number	受驗地點 check location	大腸桿菌群 colonic microbiota	採樣日期 sampling date	檢測結果 detection results
一、校本部 Main Campus				
1	行政大樓 2F保管組旁 Administrative Building 2F Next to the Custody Team	<1	112/10/04	符合規定 in compliance with regulations
2	資電館資工系 830 Department of Information and Electronics Engineering 830	<1		
3	資電館電機系 313 Department of Electrical Engineering, Information and Electronics Building 313	<1		
4	教育館 2F辦公室 Education Building 2F Office	<1		
5	化工館 4F Chemical Industry Building 4F	<1		
6	化學館 1F交誼廳 Chemistry Building 1F Social Hall	<1		
7	工程一館工工系 2F Department of Engineering, Building 1, 2F	<1		
8	育成中心政經學院 2F靠機房茶水間 2F, Computer Room tea room , School of Political Science and Economics, Incubation Center	<1		
9	第二招待所 1F餐廳 Second Guest House 1F Restaurant	<1		
10	體育館 119(右) Gymnasium 119(right)	<1		
11	東院幼兒園 10號 East Campus Kindergarten No. 10	<1		
12	義齋1F 101旁 Yi Zhai 1F next to 101	<1		
13	義齋1F 117旁 Yi Zhai 1F next to 117	<1		
14	碩齋2F 202旁 Shuo Zhai 2F next to 202	<1		
15	碩齋2F 220旁 Shuo Zhai 2F next to 220	<1		
16	信A齋3F 浴室 Shinn A Zhai 3F Bathroom	<1		
17	信B齋1F 浴室 Shinn B Zhai 3F Bathroom	<1		
18	文齋3F 302 Wen Zhai 3F 302	<1		

19	文齋4F 402 Wen Zhai 4F 402	<1		
20	文齋4F 422 Wen Zhai 4F 422	<1		
21	文齋5F 502 Wen Zhai 5F 502	<1		
	以下空白 Blank below			
二、南大校區 NTU campus				
1	學生活動中心2F-洗手間旁 Student Activity Center 2F-Next to the restroom	<1	112/10/04	符合規定 in compliance with regulations
2	體健大樓3F-廁所旁 Physical Fitness Building-3F-next to the toilet	<1		
3	推廣教育大樓 2F-後端洗手間旁 Extension Education Building 2F-Next to the restroom at the back end	<1		
	以下空白 Blank below			
<p>註1.飲用水水質標準 Note 1. Drinking water quality standards. 大腸桿菌群colonic microbiota : 6 (CFU/100mL)</p>				