

國立清華大學水質檢驗結果一覽表
National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	人文劇場 Humanities Theater	D102	<1	112/11/15	符合規定 in compliance with regulations
2	清華實驗室(220V) Tsing Hua Laboratory	1F茶水間 Pantry Room	<1	112/11/15	
3	原子爐 Nuclear Reactor Building	1F應變中心 Emergency operations center	<1	112/11/15	
4	資電館電機系 Electrical Engineering and Computer Science Building : Department of Electrical Engineering	211室 Room211	<1	112/11/15	
5	資電館電機系 Electrical Engineering and Computer Science Building : Department of Electrical Engineering	824室 Room824	<1	112/11/15	
6	教育館 Education Building	3F管理員室 Administrator's Office	<1	112/11/15	
7	工程一館動機館 Engineering Building I : Department of Power Mechanical Engineering	201室 Room201	<1	112/11/15	
8	化工館 Department of Chemical Engineering	216室 Room216	<1	112/11/15	
9	動化館 Chemistry and Power Mechanical Engineering	214室 Room214	<1	112/11/15	
10	化學館 Department of Chemistry	4F	<1	112/11/15	
11	化學館 Department of Chemistry	7F	<1	112/11/15	
12	台積館 TSMC Building	9F茶水間 Pantry Room	<1	112/11/15	
13	雅齋 (Dorm Ya)	地下室 (basement)	<1	112/11/15	
14	文齋 (Dorm Wen)	一樓102 (102, first floor)	<1	112/11/15	
15	明齋 (Dorm Ming)	一樓浴室 (First floor bathroom)	<1	112/11/15	
16	善齋 (Dorm Shan)	二樓走廊 (Second floor corridor)	<1	112/11/15	
17	學齋(Dorm Shiue) C棟 (Building C)	七樓 (seventh floor)	<1	112/11/15	
18	儒齋 (Dorm Ru) A棟 (Building A)	一樓 (first floor)	<1	112/11/15	
19	禮齋 (Dorm Li)	一樓102 (102, first floor)	<1	112/11/15	
20	鴻齋 (Dorm Hung)	二樓洗衣間 (Laundry room on the second floor)	<1	112/11/15	
21	清齋(Dorm Tsing) B棟 (Building B)	一樓洗衣間 (First floor laundry room)	<1	112/11/15	
22	實齋 (Dorm Shyr)	一樓交誼廳 (Social room on the first floor)	<1	112/11/15	
	以下空白 Blank below				

二、國立清華大學南大校區 新竹市東區大路521號
National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City

1	體健大樓-3F-305室旁 Health and Physical Education Building-- 3rd Floor-- beside Room 305		<1	112/11/15	符合規定 in compliance with regulations
2	推廣教育大樓-3F-後端洗手間旁 Extended Education Building-- 3rd Floor-- beside back toilet		<1	112/11/15	
3	鳴鳳樓-1F-樓梯旁 Ming Feng Dorms-- 1st Floor-- beside stairway		<1	112/11/15	
4	崇善樓-3F-洗手間旁 Chung Shan Dorms-- 3rd Floor-- beside toilet		<1	112/11/15	
	以下空白 Blank below				

註1. 飲用水水質標準 Note 1. Drinking water quality standards.

大腸桿菌群 colonic microbiota : 6 (CFU/100mL)

