

國立清華大學水質檢驗結果一覽表
National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
-----------	--------------------------------------	--------------------------------	-------------------	-------------------------	----------------------

一、國立清華大學新竹市東區光復路2段101號
 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City

1	人文劇場 Humanities Theater	D102	<1	112/12/6	符合規定 in compliance with regulations
2	台積館 TSMC Building	二樓茶水間 2F Pantry Room	<1	112/12/6	
3	台積館 TSMC Building	七樓茶水間 7F Pantry Room	<1	112/12/6	
4	綜三大樓數學系 General Building III : Department of Mathematics	707教授休息室 Faculty Lounge	<1	112/12/6	
5	物理館 Physics Building	B1(大廳 Lobby)	<1	112/12/6	
6	物理館 Physics Building	6F(621旁 Next to the room621)	<1	112/12/6	
7	資電館電機系 Electrical Engineering and Computer Science Building : Department of Electrical Engineering	418室 Room418	<1	112/12/6	
8	資電館電機系 Electrical Engineering and Computer Science Building : Department of Electrical Engineering	624室 Room624	<1	112/12/6	
9	化工館 Department of Chemical Engineering	6F	<1	112/12/6	
10	化學館 Department of Chemistry	B1茶水間 Pantry Room	<1	112/12/6	
11	工程一館工工系 Engineering Building I : Department of Industrial Engineering and Engineering Management	7F	<1	112/12/6	
12	工程一館工工系 Engineering Building I : Department of Industrial Engineering and Engineering Management	9F	<1	112/12/6	
13	網球場 Tennis Court	1F	<1	112/12/6	
14	鴻齋 (Dorm Hung) A棟(Building A)	一樓洗衣間 (First floor laundry room)	<1	112/12/6	
15	信齋 (Dorm Shinn)	一樓浴室(First floor bathroom)	<1	112/12/6	
16	碩齋 (Dorm Shuo)	一樓102(102, first floor)	<1	112/12/6	
17	靜齋 (Dorm Jing)	二樓廚房(Second floor kitchen)	<1	112/12/6	
	以下空白				

二、國立清華大學南大校區 新竹市東區大路521號
 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City

1	樹德樓-1F-108室旁 Shu Te Dorm-1F-beside 108 Room		<1	112/12/6	符合規定 in compliance with regulations
2	樹德樓-4F-412室旁 Shu Te Dorm-4F-beside 412 Room		<1	112/12/6	
3	樹德樓-1F-男宿入口處 Shu Te Dorm-1F-the entrance of male Dorm		<1	112/12/6	
4	菊月齋-1F Chu Yueh Dorm-1F		<1	112/12/6	
5	藝設系大樓-3F-電梯邊 The Building of Art and Design Department-3F-beside stairway		<1	112/12/6	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
 大腸桿菌群 Coliform : 6 (CFU/100mL)

