

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	行政大樓 Administration Building	3F校園規劃室前右 To the right in front of the Division of Campus Planning	<1	113/11/6	符合規定 in compliance with regulations
2	科儀館 Scientific Instrument Center	2F	<1	113/11/6	
3	資電館實工系 Electrical Engineering and Computer Science Building : Department of Computer Science	320室 Room320	<1	113/11/6	
4	桌球館 Table Tennis Arena	左側 Left side	<1	113/11/6	
5	風雲樓 Feng Yun Building	3F門口 Doorway	<1	113/11/6	
6	生醫科學系 Department of Biomedical Engineering & Environmental Sciences	404室 Room404	<1	113/11/6	
7	工科館 Engineering and System Science Building	WEF 1F(左)走廊 Corridor on the left	<1	113/11/6	
8	工科館 Engineering and System Science Building	4F走廊425室旁 Corridor next to the Room425	<1	113/11/6	
9	生科二館 Life Science Building II	1F大廳 Lobby (Right side)	<1	113/11/6	
10	生科二館 Life Science Building II	612室 Room612	<1	113/11/6	
11	清華實驗室(220V) Tsing Hua Laboratory(220V)	318室(110V) Room 318 (110V)	<1	113/11/6	
12	台積館 TSMC Building	三樓廁所旁 3F Next To The Restroom	<1	113/11/6	
13	台積館 TSMC Building	七樓廁所旁 7F Next To The Restroom	<1	113/11/6	
14	義齋(Dorm Ping)	4樓417旁(Next to 401 on the 4th floor)	<1	113/11/6	
15	清齋(Dorm Tsing)	B棟(Building B) 3樓洗衣間(Laundry room on the third floor)	<1	113/11/6	
16	清齋(Dorm Tsing)	D棟(Building D) 2樓洗衣間 (Laundry room on the second floor)	<1	113/11/6	
17	碩齋(Dorm Shuo)	3樓302旁(Next to 302 on the 3rd floor)	<1	113/11/6	
18	鴻齋(Dorm Jen)	5樓洗衣間(Laundry room on the 5th floor)	<1	113/11/6	
19	儒齋(Dorm Shinn)	A棟(Building A) 5樓 (5th floor)	<1	113/11/6	
20	學齋(Dorm Shiu)	B棟(Building B) 4樓(4th floor)	<1	113/11/6	
21	儒齋(Dorm Ru)	C棟(Building C) 3樓(3th floor)	<1	113/11/6	
22	靜齋(Dorm Jing)	洗手間旁 Next to the restroom	<1	113/11/6	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大馬路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	綜合教學大樓-3F-309室 General Education Building-309 Room		<1	113/11/6	符合規定 in compliance with regulations
2	綜合教學大樓-3F-後端茶水間 General Education Building-3F-the back tea room		<1	113/11/6	
3	綜合教學大樓-5F-後端茶水間 General Education Building-5F-the back tea room		<1	113/11/6	
4	數理教育大樓-5F-右側樓梯間 Mathematics and Science Education Building-5F-the right staircase		<1	113/11/6	
5	推廣教育大樓-1F-英語教學系 Extended Education Building-1F-Department of English Instruction		<1	113/11/6	
6	推廣教育大樓-3F-計網中心 Extended Education Building-3F-Computer and Network Center		<1	113/11/6	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)

