

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	人文劇場 Humanities Theater	D202	<1	114/12/3	符合規定 in compliance with regulations
2	台積館 TSMC Building	二樓茶水間 2F Pantry Room	<1	114/12/3	
3	台積館 TSMC Building	七樓茶水間 7F Pantry Room	<1	114/12/3	
4	綜三大樓數學系 General Building III : Department of	707教授休息室 Faculty Lounge	<1	114/12/3	
5	物理館 Physics Building	B1(大廳 Lobby)	<1	114/12/3	
6	物理館 Physics Building	6F	<1	114/12/3	
7	資電館電機系 Electrical Engineering and Computer Science Building : Department of Electrical Engineering	418室 Room418	<1	114/12/3	
8	資電館電機系 Electrical Engineering and Computer Science Building : Department of Electrical Engineering	624室 Room624	<1	114/12/3	
9	網球場 Tennis Court	1F	<1	114/12/3	
10	化工館 Department of Chemical Engineering	6F	<1	114/12/3	
11	化學館 Department of Chemistry	B1茶水間 Pantry Room	<1	114/12/3	
12	工程一館工工系 Engineering Building I : Department of Industrial Engineering and Engineering Management	7F	<1	114/12/3	
13	工程一館工工系 Engineering Building I : Department of Industrial Engineering and Engineering Management	9F	<1	114/12/3	符合規定 in compliance with regulations
14	文學館 Museum of Literature	1F	<1	114/12/3	
15	教育大樓 Faculty of Education Building	Room108	<1	114/12/3	
16	教育大樓 Faculty of Education Building	Room310	<1	114/12/3	
17	教育大樓 Faculty of Education Building	Room514	<1	114/12/3	
18	綠能大樓 Green Energy Research and Education Building	4F 茶水間 Pantry Room	<1	114/12/3	
19	清齋 (Dorm Tsing)	B棟 (Building B) 1樓洗衣間 (5th Floor Lounge)	<1	114/12/3	
20	清齋 (Dorm Tsing)	B棟 (Building B) 8樓洗衣間 (8th Floor Laundry Room)	<1	114/12/3	
21	清齋 (Dorm Tsing)	DE棟 (Building DE) 5樓電梯前 (In front of the elevator on the 5th floor)	<1	114/12/3	
22	清齋 (Dorm Tsing)	D棟 (Building D) 8樓洗衣間 (8th Floor Laundry Room)	<1	114/12/3	
23	學齋 (Dorm Shiu)	A棟 (Building A) 5樓交誼廳 (5th Floor Lounge)	<1	114/12/3	符合規定 in compliance with regulations
24	雅齋 (Dorm Ya)	3樓328(3rd Floor,302)	<1	114/12/3	
25	文齋 (Dorm Wen)	3樓(3rd Floor,302)	<1	114/12/3	
26	儒齋 (Dorm Ru)	A棟 (Building A) 7樓 (7th Floor Lounge)	<1	114/12/3	
27	儒齋 (Dorm Ru)	C棟 (Building C) 二樓交誼廳 (2nd Floor Lounge)	<1	114/12/3	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	樹德樓-1F-108室旁 Shu Te Dorm-1F-beside 108 Room		<1	114/12/3	符合規定 in compliance with regulations
2	樹德樓-1F-男宿入口處 Shu Te Dorm-1F-the entrance of men's Dorm		<1	114/12/3	
3	拘月齋-1F Chu Yueh Dorm-1F		<1	114/12/3	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100ml.)

