

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	台積館 TSMC Building	一樓茶水間 1F Pantry Room	<1	114/1/8	符合規定 in compliance with regulations
2	台積館 TSMC Building	八樓廁所旁 8F Next To The Restroom	<1	114/1/8	
3	駕駛班 Driver's Office	門口 Doorway	<1	114/1/8	
4	綜二大樓教務處 General Building II : Office of Academic	6F茶水間 Pantry Room (220V)	<1	114/1/8	
5	第二招待所 Guest House II	3F	<1	114/1/8	
6	綠能教學大樓 Green Energy Research and Education Building (Lee Tsen Min Building)	2F茶水間 Pantry Room	<1	114/1/8	
7	蒙民偉樓 Mong Man Wai Building	4F	<1	114/1/8	
8	綜二大樓天文所 General Building II : Institute of Astronomy	B1茶水間 Pantry Room (R)	<1	114/1/8	
9	綜二大樓電子所 General Building II : Institute of Electronics	3F普物教室旁 Next To The General Physics Laboratory	<1	114/1/8	
10	綜三大樓數學系 General Building III : Department of	5F茶水間 Pantry Room	<1	114/1/8	
11	物理館 Physics Building	2F(221旁 Next to the room221)	<1	114/1/8	
12	教育館 Education Building	1F側門入口 Side Entrance	<1	114/1/8	
13	台達館材料系 Delta Hall : Department of Materials Science and Engineering	B1-璟德演講廳門口 At the door of Jingde Lecture Hall	<1	114/1/8	
14	旺宏館圖書館 Macronix Building : Library	4F K書中心 Study Room(左 Left side)	<1	114/1/8	
15	工程一館 Engineering Building I	3F動機系教職員休息室 Department of PowerMechanicalEngineering Faculty Lounge	<1	114/1/8	
16	工程一館工工系 Engineering Building I : Department of Industrial Engineering and Engineering Management	106	<1	114/1/8	
17	華齋(Dorm Hua)	204對面(Opposite 204)	<1	114/1/8	
18	善齋(Dorm Shan)	2樓走廊 92nd floor corridor	<1	114/1/8	
19	新齋(Dorm Hsing)	3樓管理室旁(Next to the management room on the 3rd	<1	114/1/8	
20	學齋(Dorm Shiue)	B棟(Building B) 5樓(5th floor)	<1	114/1/8	
21	清齋(Dorm Tsing)	AB棟(Building AB) 9樓電梯前(In front of the elevator on the 9th floor)	<1	114/1/8	
22	仁齋(Dorm Jen)	4樓412旁(Next to 412 on the 4th floor)	<1	114/1/8	
23	碩齋(Dorm Shuo)	2樓236旁(Next to 236 on the 2nd floor)	<1	114/1/8	
24	信齋(Dorm Shinn)	A棟(Building A) 4樓浴室(4th floor bathroom)	<1	114/1/8	
25	文齋(Dorm Wen)	5樓502(502, 5th floor)	<1	114/1/8	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards  
大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	行政大樓-1F-竹松社區大學 Administration Building-1F-Green Pine Community College		<1	114/1/8	符合規定 in compliance with regulations
2	圖書館(南大分館)-1F-電梯旁 Library Nanda Branch-1F-beside elevator		<1	114/1/8	
3	綜合教學大樓-3F-前端茶水間 General Education Building-3F-the front tea room		<1	114/1/8	
4	教學大樓-3F-2304室旁 Education Building-3F-beside 2304 Room		<1	114/1/8	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards  
大腸桿菌群 Coliform : 6 (CFU/100mL)

