國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List 編號 單位名稱 地點 大腸桿菌群 採樣日期 檢測結果 The name of the organization No. Location of installation Coliform Collection Date Test results 一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City 清華實驗室(220V) Tsing Hua Laboratory(220V) 9F茶水間 Pantry Room <1 113/8/7 材料科技館Materials Science & Technology Building 501室 Room501 <1 113/8/7 台達館資工系 Delta Hall: Department of Computer Science 1F-105室旁 Next to the room 105 <1 113/8/7 |台達館電機系 Delta Hall: Department of Electrical 2F-218室旁 Next to the room 218 <1 113/8/7 台達館材料系 Delta Hall: Department of Materials Science 4F-茶水間 Pantry Room <1 113/8/7 and Engineering 台達館電資院 Delta Hall: College of Electrical Engineering 3F-303 室旁 Next to the room303 <1 113/8/7 and Computer Science 台達館電資院 Delta Hall: College of Electrical Engineering 5F-茶水間 Pantry Room <1 113/8/7 and Computer Science 符合規定 in 台達館電機系 Delta Hall: Department of Electrical 8F-茶水間 Pantry Room <1 113/8/7 compliance with 清華會館 Guest House I 清齋AB棟10F Dormitory Tsing BuildingAB 10F <1 113/8/7 regulations 義齋(Dorm Yi) 3樓317旁(Next to 317 on the 3rd floor) <1 113/8/7 11 新齋(Dorm Hsin) B(Building B) 8樓B806對面(Opposite B806 on the 8th <1 113/8/7 12 |學齋(Dorm Tsing) C楝(Building C) 2樓 (2nd floor) <1 113/8/7 清齋(Dorm Tsing) D棟(Building D) 9樓洗衣間(Laundry room on the 9th <1 113/8/7 禮齋(Dorm Tsing) 4樓419旁(Next to 419 on the 4th floor) <1 113/8/7 實 齋(Dorm Shyr) 一樓浴室(1st floor bathroom) <1 113/8/7 碩齋(Dorm Shuo) 5樓536旁(Next to 536 on the 5th floor) <1 113/8/7 儒齋(Dorm Ru) D棟(Building D) 6樓(6th floor) <1 113/8/7 18 文齋(Dorm Wen) 4樓422旁(Next to 422 on the 4th floor) <1 113/8/7 以下空白

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform: 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List 編號 單位名稱 地點 大腸桿菌群 採様日期 檢測結果 No. The name of the organization Location of installation Coliform Collection Date Test results 二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City 圖書館(南大分館)-1F-休閒閱覽室 <1 Library Nanda Branch-1F-Refreshing corner 113/8/7 綜合教學大樓-B1-國際會議廳 <1 General Education Building-B1-National Conference Hall 113/8/7 符合規定 in compliance with 綜合教學大樓-2F-210室旁 <1 113/8/7 regulations General Education Building-beside 210 Room 綜合教學大樓-8F-茶水間 <1113/8/7 General Education Building-8F-Tea Room 以下空白

環境實驗室 台 北

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform: 6 (CFU/100mL)