國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	生命科學二館 Life Science Building II	612室 Room612	<1	115/11/11	符合規定 in compliance with regulations
2	台積館 TSMC Building	三樓廁所旁 3F Next To The Restroom	<1	115/11/11	
3	台積館 TSMC Building	七樓廁所旁 7F Next To The Restroom	<1	115/11/11	
4	清華實驗室(220V) Tsing Hua Laboratory(220V)	318室(110V) Room 318 (110V)	<1	115/11/11	
5	生醫科學系 Department of Biomedical Engineering & Environmental	404室 Room404	<1	115/11/11	
6	工科館 Engineering and System Science Building	WEF 1F(左)走廊 Corridor on the left	<1	115/11/11	
7	工科館 Engineering and System Science Building	4F走廊425室旁 Corridor next to the Room425	<1	115/11/11	
8	風雲樓 Feng Yun Building	3F門口 Doorway	<1	115/11/11	
9	資電館資工系 Electrical Engineering and Computer Science Building：Department of Computer Science	320室 Room320	<1	115/11/11	
10	桌球館 Table Tennis Arena	左側 Left side	<1	115/11/11	
11	行政大樓 Administration Building	3F校園規劃室前右 To the right in front of the Division of Campus Planning	<1	115/11/11	
12	科儀館 Scientific Instrument Center	2F	<1	115/11/11	
13	生科二館 Life Science Building II	1F大廳(右) Lobby (Right side)	<1	115/11/11	
14	舊育成中心 Old Center of Innovation Incubator	2F茶水間 2F Pantry Room	<1	115/11/11	
15	誠齋(Dorm Cheng)	1樓樓梯西 (West side of the first-floor stairs)	<1	115/11/11	
16	義齋(Dorm Yi)	4樓401旁(Next to 401 on the 4th floor)	<1	115/11/11	
17	學齋(Dorm Shiue)	B棟(Building B) 4樓 (4th floor)	<1	115/11/11	
18	清齋(Dorm Tsing)	AB棟(Building AB) 4樓電梯前(In front of the elevator on the 4th floor)	<1	115/11/11	
19	清齋(Dorm Tsing)	B棟(Building B) 3樓洗衣間(3rd Floor Laundry Room)	<1	115/11/11	
20	清齋(Dorm Li)	D棟(Building D) 2樓洗衣間 (2nd floor laundry room)	<1	115/11/11	
21	鴻齋(Dorm Hung)	5樓洗衣間(5th floor laundry room)	<1	115/11/11	
22	碩齋(Dorm Shuo)	3樓302旁 (Next to 302 on the 3rd floor)	<1	115/11/11	
23	儒齋(Dorm RU)	A棟(Building A) 5樓(5th floor)	<1	115/11/11	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform：6 (CFU/100mL)

台灣檢驗科技股份有限公司 環境實驗室 台北 新北市五股區五工路136-1號

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	綜合教學大樓-9F-茶水間 General Education Building-9F-Tea Room		<1	115/11/11	符合規定 in compliance with regulations
2	體健大樓-4F-405室旁 Health and Physical Education Building-4F-beside 405 Room		<1	115/11/11	
3	推廣教育大樓-1F-竹松社區大學 Extended Education Building-1F-Green Pine Community College		<1	115/11/11	
4	樹德樓-5F-洗衣機旁 Shu Te Dorm-5F-beside washing machine		<1	115/11/11	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform：6 (CFU/100mL)

台灣檢驗科技股份有限公司 環境實驗室 台北 新北市五股區五工路136-1號