

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	教育大樓 College of Education Building	629室 Room 629	<1	115/8/5	符合規定 in compliance with regulations
2	教育大樓 College of Education Building	829室 Room 829	<1	115/8/5	
3	材料科技館 Materials Science & Technology Building	501室 Room 501	<1	115/8/5	
4	台達館資工系 Delta Hall : Department of Computer Science	1F-105室旁 Next to the room 105	<1	115/8/5	
5	台達館電機系 Delta Hall : Department of Electrical Engineering	2F-218室旁 Next to the room 218	<1	115/8/5	
6	台達館材料系 Delta Hall : Department of Materials Science and	4F-茶水間 Pantry Room	<1	115/8/5	
7	台達館電資院 Delta Hall : College of Electrical Engineering and Computer Science	3F-303室旁 Next to the room 303	<1	115/8/5	
8	台達館電資院 Delta Hall : College of Electrical Engineering and Computer Science	5F-茶水間 Pantry Room	<1	115/8/5	
9	台達館電機系 Delta Hall : Department of Electrical Engineering	8F-茶水間 Pantry Room	<1	115/8/5	
10	育成中心 Center of Incubator	4F	<1	115/8/5	
11	舊育成中心 Old Center of Innovation Incubator	3F-茶水間 3F Pantry Room	<1	115/8/5	
12	義齋(Dorm Yi)	3樓317旁(Next to 317 on the 3rd floor)	<1	115/8/5	
13	學齋(Dorm Shihue)	B棟(Building B) 3樓(3rd floor)	<1	115/8/5	
14	學齋(Dorm Shihue)	C棟(Building C) 2樓(2nd floor)	<1	115/8/5	
15	清齋(Dorm Tsing)	D棟(Building D) 9樓洗衣間(9th floor laundry room)	<1	115/8/5	
16	實齋(Dorm Hsin)	1樓浴室(1st floor bathroom)	<1	115/8/5	
17	靜齋(Dorm Jing)	1F洗手間旁(Next to the bathroom)	<1	115/8/5	
18	碩齋(Dorm Shuo)	5樓536旁(Next to 536 on the 5th floor)	<1	115/8/5	
19	儒齋(Dorm Ru)	A棟(Building A) 4樓(4th floor)	<1	115/8/5	
20	儒齋(Dorm Ru)	C棟(Building C) 1樓(1st floor)	<1	115/8/5	
21	教職員宿舍	新竹市金城一路52巷7號	<1	115/8/5	
22	教職員宿舍	新竹市光復路二段101號東院87-88號	<1	115/8/5	
23	生科二館	地下室	<1	115/8/5	
24	水木餐廳	1F	<1	115/8/5	
25	工程四館	1F	<1	115/8/5	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL.)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	行政大樓-5F-右側洗手間旁 Administration Building-5F-beside right toilet		<1	115/8/5	符合規定 in compliance with regulations
2	綜合教學大樓-B1-國際會議廳 General Education Building-B1-National Conference Hall		<1	115/8/5	
3	綜合教學大樓-2F-210室旁 General Education Building-beside 210 Room		<1	115/8/5	
4	推廣教育大樓-3F-計網中心 Extended Education Building-3F-Computer and Network Center		<1	115/8/5	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)

