

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	綜二館天文所 General Building II : Institute of Astronomy	5F茶水間 Pantry Room (左 Left side)	<1	113/5/8	符合規定 in compliance with regulations
2	台達館材料系 Delta Hall : Department of Materials Science and Engineering	B1-靠籃球場廁所 Close to the basketball court restrooms	<1	113/5/8	
3	台達館資工系 Delta Hall : Department of Computer Science	1F-茶水間 Pantry Room	<1	113/5/8	
4	台達館電機系 Delta Hall : Department of Electrical	2F-217室旁 Next to the room 217	<1	113/5/8	
5	台達館電機系 Delta Hall : Department of Electrical	5F-518室旁邊 Next to the room 518	<1	113/5/8	
6	台達館電機系 Delta Hall : Department of Electrical	9F靠籃球場窗戶邊 Near the window of the basketball	<1	113/5/8	
7	台達館資工系 Delta Hall : Department of Computer Science	7F-茶水間 Pantry Room	<1	113/5/8	
8	動化館 Chemistry and Power Mechanical Engineering Building	305室 Room305	<1	113/5/8	
9	化工館 Department of Chemical Engineering	721室 Room721	<1	113/5/8	
10	清華會館 Guest House I	5F	<1	113/5/8	
11	校友體育館 Alumni Gymnasium	1F	<1	113/5/8	
12	駐警隊 Campus Security Office	1F	<1	113/5/8	
13	綠能教學大樓 Green Energy Research and Education Building (Lee Tsen Min Building)	3F茶水間 Pantry Room	<1	113/5/8	
14	台積館 TSMC Building	六樓茶水間 6F Pantry Room	<1	113/5/8	
15	清華實驗室(220V) Tsing Hua Laboratory(220V)	6F茶水間 Pantry Room	<1	113/5/8	
16	雅齋(Dorm Ya)	1樓122(122, 1st floor)	<1	113/5/8	
17	新齋(Dorm Hsin)	7樓A區(Area A, 7th Floor)	<1	113/5/8	
18	禮齋(Dorm Li)	1樓119(1st floor 119)	<1	113/5/8	
19	儒齋(Dorm Ru)	A棟(Building A) 4樓(4th floor)	<1	113/5/8	
20	信齋(Dorm Shinn)	A棟(Building A) 二樓浴室(2nd floor bathroom)	<1	113/5/8	
21	善齋(Dorm Shan)	1樓廚房(1st floor kitchen)	<1	113/5/8	
22	鴻齋(Dorm Hung)	7樓(7th floor laundry room)	<1	113/5/8	
23	學齋(Dorm Shiue)	D棟(Building D) 3樓(6th floor)	<1	113/5/8	
24	清齋(Dorm Tsing)	B棟(Building B) 7樓洗衣間(7th floor laundry room)	<1	113/5/8	
25	清齋(Dorm Tsing)	AB棟(Building AB) 3樓電梯前(In front of the elevator on the 3rd floor)	<1	113/5/8	
	以下空白				



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	行政大樓-1F-總務處茶水間 Administration Building-1F-Pantry Room of General Affair		<1	113/5/8	符合規定 in compliance with regulations
2	竹師會館-1F-樓梯口 National Hsinchu University of Education History Gallery-1F-staircase		<1	113/5/8	
3	推廣教育大樓-2F-前端洗手間旁 Extended Education Building-2F-beside front toilet		<1	113/5/8	
4	推廣教育大樓-4F-9431室(台語所辦公室) Extended Education Building-9431 Room(office for Institute of Taiwan Languages and Language Teaching)		<1	113/5/8	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)

