


國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	清華實驗室(220V) Tsing Hua Laboratory(220V)	8F茶水間 Pantry Room	<1	115/6/10	符合規定 in compliance with regulations
2	教育大樓 Faculty of Education Building	5F兩梯旁5F Next To The Elevator 丙	<1	115/6/10	
3	教育大樓 Faculty of Education Building	721室 Room721	<1	115/6/10	
4	綠能教學大樓 Green Energy Research and Education Building (Lee Tsen Min Building)	4F茶水間 Pantry Room	<1	115/6/10	
5	綜二大樓奈微所 General Building II : Institute of NanoEngineering and MicroSystems	8F茶水間 Pantry Room	<1	115/6/10	
6	綜三大樓理學院 General Building III : College of Science	地下室 Basement	<1	115/6/10	
7	體育館 Education Building	107室 Room107	<1	115/6/10	
8	清華會館 Guest House I	8F	<1	115/6/10	
9	大門口 Main Gate	收費亭 Toll Station	<1	115/6/10	
10	工程一館動機館 Engineering Building I : Department of Power Mechanical Engineering	301室 Room301	<1	115/6/10	
11	化工館 Department of Chemical Engineering	521室 Room521	<1	115/6/10	
12	化學館 Department of Chemistry	6F	<1	115/6/10	
13	台達館材料系 Delta Hall : Department of Materials Science and	B1-111休息室 111 Lounge	<1	115/6/10	
14	台達館奈微所 Delta Hall : Institute of NanoEngineering and	3F-茶水間 Pantry Room	<1	115/6/10	
15	台達館資工系 Delta Hall : Department of Computer Science	6F-茶水間 Pantry Room	<1	115/6/10	
16	學齋(Dorm D)	D棟(Building D) 3樓 (3rd floor)	<1	115/6/10	
17	碩齋(Dorm Shuo)	5樓502旁(Next to Room 502 on the 5th floor)	<1	115/6/10	
18	碩齋(Dorm Shuo)	1樓102旁(Next to 102 on the 1st floor)	<1	115/6/10	
19	清齋(Dorm Tsing)	D棟(Building D) 1樓洗衣間(1st floor laundry room)	<1	115/6/10	
20	清齋(Dorm Tsing)	B棟(Building B) 7樓洗衣間(7th Floor Laundry Room)	<1	115/6/10	
21	清齋(Dorm Li)	DE棟(Building DE) 10樓電梯前 (In front of the elevator on the 10th floor)	<1	115/6/10	
22	鴻齋(Dorm Hung)	2樓洗衣間(2nd floor laundry room)	<1	115/6/10	
23	信齋(Dorm Jen)	A棟(Building A) 2樓浴室(2nd floor bathroom)	<1	115/6/10	
24	儒齋(Dorm RU)	A棟(Building A) 1樓(1st Floor)	<1	115/6/10	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	行政大樓-4F-右側洗手間旁 Administration Building-4F-beside right toilet		<1	115/6/10	符合規定 in compliance with regulations
2	圖書館(南大分館)-4F-電梯旁 Library Nanda Branch-4F-beside elevator		<1	115/6/10	
3	綜合教學大樓-2F-後端茶水間 General Education Building-2F-the back tea room		<1	115/6/10	
4	飲虹樓-1F-教職員宿舍 Yin Hong Dorm-1F-Dorm for staff		<1	115/6/10	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)

