


國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	台積電 TSMC Building	五樓廁所旁 5F Next To The Restroom	<1	115/2/4	符合規定 in compliance with regulations
2	清華實驗室(220V) Tsing Hua Laboratory	3F茶水間 Pantry Room	<1	115/2/4	
3	清華實驗室(220V) Tsing Hua Laboratory	5F茶水間 Pantry Room	<1	115/2/4	
4	教育大樓 Faculty of Education Building	210室 Room210	<1	115/2/4	
5	教育大樓 Faculty of Education Building	729室 Room729	<1	115/2/4	
6	生醫科學系 Department of Biomedical Engineering & Environmental Sciences	116室 Room116	<1	115/2/4	
7	材料科技館 Materials Science & Technology Building	102A室 Room102A	<1	115/2/4	
8	清華會館 Guest House I	4F	<1	115/2/4	
9	清華會館 Guest House I	7F	<1	115/2/4	
10	男單宿舍 Women's Single Dormitory	1F	<1	115/2/4	
11	莊敬樓 Chung Ching Faculty Residences	1F	<1	115/2/4	
12	行政大樓 Administration Building	1F大廳 Lobby	<1	115/2/4	
13	行政大樓 Administration Building	1F出納組 Division of Cashier	<1	115/2/4	
14	行政大樓 Administration Building	3F學務長室旁右 On the right next to the Dean Office of Student Affairs	<1	115/2/4	
15	綜四館教務處 General Building IV : Office of Academic Affairs	2F廁所旁(右) Next To The Restroom(Right side)	<1	115/2/4	
16	工程一館動機館 Engineering Building I : Department of Power Mechanical Engineering	401室 Room401	<1	115/2/4	
17	科儀館 Scientific Instrument Center	1F	<1	115/2/4	
18	化學館 Department of Chemistry	3F	<1	115/2/4	
19	義齋(Dorm Yi)	1樓101旁(Next to 101 on the first floor)	<1	115/2/4	
20	清齋(Dorm Tsing)	DE棟(Building DE) 2樓電梯前(In front of the elevator on the 2nd floor)	<1	115/2/4	
21	新齋(Dorm Hsing)	4樓A411對面(Opposite 4th Floor, A411)	<1	115/2/4	
22	學齋(Dorm Shiu)	D棟(Building D) 2樓(Second floor)	<1	115/2/4	
23	仁齋(Dorm Jen)	3樓301旁(Next to Room 301 on the 3rd floor)	<1	115/2/4	
24	禮齋(Dorm Li)	4樓419旁(Next to 419 on the 4th floor)	<1	115/2/4	
25	鴻齋(Dorm Hung)	8樓洗衣間(8th Floor Laundry Room)	<1	115/2/4	
26	實齋(Dorm Shyr)	2樓浴室東(Bathroom East, 2nd Floor)	<1	115/2/4	
27	儒齋(Dorm Ru)	B棟(Building B) 7樓(7th floor)	<1	115/2/4	
28	文齋(Dorm Wen)	4樓402(4th Floor, Room 402)	<1	115/2/4	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	崇善樓-2F-洗手間旁 Chung Shan Dorm-2F-beside toilet		<1	115/2/4	符合規定 in compliance with regulations
2	迎曦軒-4F-後棟樓梯旁 Ying His Dorm-4F-the back building beside stairway		<1	115/2/4	
3	樹德樓-5F-512室旁 Shu Te Dorm-5F-beside 512 Room		<1	115/2/4	
4	樹德樓-2F-洗衣機旁 Shu Te Dorm-2F-beside washing machine		<1	115/2/4	
	以下空白				
註1.飲用水水質標準 Note 1. Drinking water quality standards 大腸桿菌群 Coliform : 6 (CFU/100mL)					

