


國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	台積電 TSMC Building	五樓茶水間 5F Pantry Room	<1	115/4/8	符合規定 in compliance with regulations
2	清華實驗室(220V) Tsing Hua Laboratory(220V)	2F茶水間 Pantry Room	<1	115/4/8	
3	清華實驗室(220V) Tsing Hua Laboratory	7F茶水間 Pantry Room	<1	115/4/8	
4	教育大樓 Faculty of Education Building	B103	<1	115/4/8	
5	教育大樓 Faculty of Education Building	442	<1	115/4/8	
6	綠能教學大樓 Green Energy Research and Education Building (Lee Tsen Min Building)	1F茶水間 Pantry Room	<1	115/4/8	
7	綠能教學大樓 Green Energy Research and Education Building (Lee Tsen Min Building)	5F茶水間 Pantry Room	<1	115/4/8	
8	綜二大樓教務處 General Building II : Office of Academic Affairs	1F茶水間 Pantry Room	<1	115/4/8	
9	綜二大樓天文所 General Building II : Institute of Astronomy	5F茶水間 右Pantry Room (Right)	<1	115/4/8	
10	綜三大樓理學院 General Building III : College of Science	4F辦公室旁 Next to the office	<1	115/4/8	
11	物理館 Physics Building	7F(男廁旁 Next to the men's room)	<1	115/4/8	
12	化學館 Department of Chemistry	5F	<1	115/4/8	
13	育成中心 Center of Incubator	1F	<1	115/4/8	
14	育成中心 Center of Incubator	4F	<1	115/4/8	
15	清華幼稚園 Tsing Hua Kindergarten	東院10(1) East Yuan Faculty Residences No.10 (1)	<1	115/4/8	
16	義齋(Dorm Yi)	1樓117旁(Next to 117 on the first floor)	<1	115/4/8	
17	誠齋(Dorm Cheng)	1樓電梯東(First floor elevator east)	<1	115/4/8	
18	明齋(Dorm Ming)	3樓浴室(Third floor bathroom)	<1	115/4/8	
19	華齋(Dorm Hua)	1樓104對面 (Opposite 104 on the 1st floor)	<1	115/4/8	
20	善齋(Dorm Shan)	1樓廚房(1st floor kitchen)	<1	115/4/8	
21	新齋(Dorm Hsin)	2樓B211對面 (Opposite B211 on the 2nd floor)	<1	115/4/8	
22	學齋(Dorm Shiue)	B棟(Building B) 7樓 (7th floor)	<1	115/4/8	
23	鴻齋(Dorm Hung)	7樓洗衣間(7th floor laundry room)	<1	115/4/8	
24	碩齋(Dorm Shuo)	1樓102旁(Next to 102 on the first floor)	<1	115/4/8	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	行政大樓-2F茶水間 Administration Building-2F-Tea Room		<1	115/4/8	符合規定 in compliance with regulations
2	藝設系大樓-3F-電梯邊 Art and Design Building-3F-beside elevator		<1	115/4/8	
3	樹德樓-1F-洗衣機旁 Shu Te Dorm-1F-beside washing machine		<1	115/4/8	
4	樹德樓-4F-洗衣機旁 Shu Te Dorm-4F-beside washing machine		<1	115/4/8	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)

