

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	台積館 TSMC Building	一樓廁所旁 1F Next To The Restroom	<1	115/7/1	符合規定 in compliance with regulations
2	南門 South Gate	收費亭 Toll Station	<1	115/7/1	
3	教育大樓 College of Education Building	3F丙梯旁 3F Next To The Elevator 丙	<1	115/7/1	
4	工科新館 Engineering and System Science New Building	4F	<1	115/7/1	
5	工科館 Engineering and System Science Building	4F走廊402E室旁 Corridor next to the Room402E	<1	115/7/1	
6	綜二大樓學科所 4F General Building II : Institute of Learning Sciences and Technologies 4F	4F教授休息室 Faculty Lounge	<1	115/7/1	
7	物理館 Physics Building	4F	<1	115/7/1	
8	清華會館 Guest House I	6F	<1	115/7/1	
9	女單宿舍 Women's Single Dormitory	1F	<1	115/7/1	
10	諮商中心 Counseling Center	2F	<1	115/7/1	
11	綜四館教務處 General Building IV : Office of Academic Affairs	2F廁所旁(左) Next To The Restroom(Left side)	<1	115/7/1	
12	化工館 Department of Chemical Engineering	1F閱覽室 Reading Room	<1	115/7/1	
13	台達館材料系 Delta Hall : Department of Materials Science and	B1-B12對面 Opposite to Room B12	<1	115/7/1	
14	台達館電機系 Delta Hall : Department of Electrical Engineering	2F-203室旁 Next to the room 203	<1	115/7/1	
15	台達館材料系 Delta Hall : Department of Materials Science and	4F-432室 Room432	<1	115/7/1	
16	台達館電機系 Delta Hall : Department of Electrical Engineering	9F-936室旁 Next to the room 936	<1	115/7/1	
17	育成中心 Center of Incubator	6F	<1	115/7/1	
18	舊育成中心 Old Center of Innovation Incubator	1F茶水間 1F Pantry Room	<1	115/7/1	
19	新齋(Dorm Hsin)	7樓A區(7th Floor, Area A)	<1	115/7/1	
20	學齋(Dorm Shiue)	C棟(Building C) 1樓 (1st floor)	<1	115/7/1	
21	學齋(Dorm Shiue)	D棟(Building D) 1樓 (1st floor)	<1	115/7/1	
22	清齋(Dorm Tsing)	B棟(Building B) 2樓洗衣間 (2nd floor laundry room)	<1	115/7/1	
23	實齋(Dorm Hsin)	1樓浴室 (1st floor bathroom)	<1	115/7/1	
24	信齋(Dorm Hsin)	C棟(Building C) 2樓浴室 (2nd floor bathroom)	<1	115/7/1	
25	碩齋(Dorm Shuo)	2樓220旁 (Next to Room 220 on the 2nd floor)	<1	115/7/1	
26	儒齋(Dorm Ru)	A棟(Building A) 3樓(3rd floor)	<1	115/7/1	
27	儒齋(Dorm Ru)	D棟(Building D) 5樓 (5th floor)	<1	115/7/1	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	學生第一活動中心-4F-洗手間旁 Student Activity Center I-4F-beside toilet		<1	115/7/1	符合規定 in compliance with regulations
2	體健大樓-4F-廁所旁 Health and Physical Education Building-4F-beside toilet		<1	115/7/1	
3	數理教育大樓-4F-右側樓梯間 Mathematics and Science Education Building-4F-the right staircase		<1	115/7/1	
4	推廣教育大樓-2F-前端洗手間旁 Extended Education Building-2F-beside front toilet		<1	115/7/1	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)

