

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	台積館 TSMC Building	六樓茶水間 6F Pantry Room	<1	115/5/13	符合規定 in compliance with regulations
2	清華實驗室(220V) Tsing Hua Laboratory	6F茶水間 Pantry Room	<1	115/5/13	
3	教育大樓 Faculty of Education Building	2F丙梯旁 2F Next To The Elevator 丙	<1	115/5/13	
4	教育大樓 Faculty of Education Building	609室 Room609	<1	115/5/13	
5	綠能教學大樓 Green Energy Research and Education Building (Lee Tsen Min Building)	3F茶水間 Pantry Room	<1	115/5/13	
6	駐警隊 Campus Security Office	1F	<1	115/5/13	
7	校友體育館 Alumni Gymnasium	1F	<1	115/5/13	
8	清華會館 Guest House I	5F	<1	115/5/13	
9	化工館 Department of Chemical Engineering	721室 Room721	<1	115/5/13	
10	動化館 Chemistry and Power Mechanical Engineering Building	305室 Room305	<1	115/5/13	
11	台達館材料系 Delta Hall : Department of Materials Science and	B1-靠籃球場廁所 Close to the basketball court restrooms	<1	115/5/13	
12	台達館資工系 Delta Hall : Department of Computer Science	1F-茶水間 Pantry Room	<1	115/5/13	
13	台達館電機系 Delta Hall : Department of Electrical Engineering	2F-215室旁 Next to the room 215	<1	115/5/13	
14	台達館電機系 Delta Hall : Department of Electrical Engineering	5F-518室旁邊 Next to the room 518	<1	115/5/13	
15	台達館資工系 Delta Hall : Department of Computer Science	7F-茶水間 Pantry Room	<1	115/5/13	
16	台達館電機系 Delta Hall : Department of Electrical Engineering	9F靠籃球場窗戶邊 Near the window of the basketball	<1	115/5/13	
17	綜二館天文所 General Building II : Institute of Astronomy	5F茶水間 Pantry Room (左 Left side)	<1	115/5/13	
18	靜齋(Dorm Jing)	2樓廚房(2nd floor kitchen)	<1	115/5/13	
19	文齋(Dorm Wen)	5樓502(5th Floor, 502)	<1	115/5/13	
20	雅齋(Dorm Ya)	傳達室(Communication Room)	<1	115/5/13	
21	儒齋(Dorm Ru)	C棟(Building C) 7樓 (7th floor)	<1	115/5/13	
22	信齋(Dorm Hsin)	B棟(Building B) 2樓浴室 (2nd floor bathroom)	<1	115/5/13	
23	信齋(Dorm Hsin)	A棟(Building A) 2樓浴室 (2nd floor bathroom)	<1	115/5/13	
24	碩齋(Dorm Shuo)	2樓202旁 (Next to Room 202 on the 2nd floor)	<1	115/5/13	
25	仁齋(Dorm Jen)	3樓312旁 (Next to 312 on the 3rd floor)	<1	115/5/13	
26	禮齋(Dorm Li)	1樓119(1st floor, 119)	<1	115/5/13	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	行政大樓-1F-總務處茶水間 Administration Building-1F-Pantry Room of General Affair		<1	115/5/13	符合規定 in compliance with regulations
2	圖書館(南大分館)-2F-辦公室走廊 Library Nanda Branch-2F-office corridor		<1	115/5/13	
3	綜合教學大樓-2F-前端茶水間 General Education Building-2F-the front tea room		<1	115/5/13	
4	綜合教學大樓-3F-後端茶水間 General Education Building-3F-the back tea room		<1	115/5/13	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)

