


國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	台達館材料系 Delta Hall : Department of Materials Science	B1-廁所旁 Next To The Restroom	<1	113/9/11	符合規定 in compliance with regulations
2	台達館材料系 Delta Hall : Department of Materials Science and Engineering	4F-靠籃球場窗戶邊 Near the window of the basketball court	<1	113/9/11	
3	台達館電機系 Delta Hall : Department of Electrical	8F-靠籃球場窗戶邊 Near the window of the basketball	<1	113/9/11	
4	台達館電機系 Delta Hall : Department of Electrical	9F-913室對面 Opposite to Room 913	<1	113/9/11	
5	台達館資工系 Delta Hall : Department of Computer Science	6F-靠籃球場窗戶邊 Near the window of the basketball	<1	113/9/11	
6	生命科學一館 Life Science Building I	413室 Room413	<1	113/9/11	
7	生命科學二館 Life Science Building II	535室 Room535	<1	113/9/11	
8	人文社會學院 College of Humanities and Social Sciences	A312	<1	113/9/11	
9	人文社會學院 College of Humanities and Social Sciences	B406	<1	113/9/11	
10	人文社會學院 College of Humanities and Social Sciences	A619	<1	113/9/11	
11	育成中心政經學院 Incubation Center School of Political Science and Economics	2F教授休息區 2F Faculty Lounge	<1	113/9/11	
12	工科館 Engineering and System Science Building	3F茶水間 Pantry Room	<1	113/9/11	
13	蒙民偉樓 Mong Man Wai Building	1F	<1	113/9/11	
14	名人堂 Tsing Hua Hall of Fame	2F	<1	113/9/11	
15	衛保組 Division of Health Service	1F	<1	113/9/11	
16	諮商中心 Counseling Center	1F資源教室 Resource Classroom	<1	113/9/11	
17	育成中心 Center of Incubator	8F	<1	113/9/11	
18	善齋(Dorm Shan)	1樓廚房(Ground floor kitchen)	<1	113/9/11	
19	新齋(Dorm Hsin)	5樓教官室旁(Next to the instructor's office on the 5th	<1	113/9/11	
20	華齋(Dorm Hua)	104對面 (104 opposite)	<1	113/9/11	
21	清齋(Dorm Tsing)	DE棟(Building DE) 9樓電梯前(In front of the elevator on the 9th floor)	<1	113/9/11	
22	仁齋(Dorm Jen)	4樓4401旁(Next to 401 on the 4th floor)	<1	113/9/11	
23	信齋(Dorm Shinn)	B棟(Building B) 3樓浴室(Bathroom on the third floor)	<1	113/9/11	
24	學齋(Dorm Shiue)	A棟(Building A) 2樓(2nd floor)	<1	113/9/11	
25	儒齋(Dorm Ru)	B棟(Building B) 3樓(3rd floor)	<1	113/9/11	
26	慧齋(Dorm Huei)	1樓廚房(Ground floor kitchen)	<1	113/9/11	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	行政大樓-5F-右側洗手間旁 Administration Building-5F-beside right toilet		<1	113/9/11	符合規定 in compliance with regulations
2	圖書館(南大分館)-5F-電梯旁 Library Nanda Branch-5F-beside elevator		<1	113/9/11	
3	綜合教學大樓-2F-後端茶水間 General Education Building-2F-the back tea room		<1	113/9/11	
4	綜合教學大樓-7F-茶水間 General Education Building-7F-Tea Room		<1	113/9/11	
	以下空白				

註1. 飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)

