

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	生命科學一館 Life Science Building I	315室 Room315	<1	113/12/11	
2	生命科學二館 Life Science Building II	313室 Room313	<1	113/12/11	
3	人文社會學院 College of Humanities and Social Sciences	A523	<1	113/12/11	
4	人文社會學院 College of Humanities and Social Sciences	C507	3	113/12/11	
5	育成中心政經學院 Incubation Center School of Political Science and Economics	2F院長室旁茶水間 2F Pantry Room next to the Superintendent Office	<1	113/12/11	
6	學士後醫系 School of Post-Baccalaureate Medicine	育成中心3F茶水間 Center of Incubator 3F Pantry Room	<1	113/12/11	
7	工科館 Engineering and System Science Building	4F教授休息室 421室 Faculty Lounge Room421	<1	113/12/11	
8	蒙民偉樓 Mong Man Wai Building	5F	<1	113/12/11	
9	名人堂 Tsing Hua Hall of Fame	1F	<1	113/12/11	
10	水木生活中心 Shui Mu Student Center	2F	<1	113/12/11	
11	風雲樓 Feng Yun Building	2F電梯旁 Next to the elevator	<1	113/12/11	
12	學人宿舍 Guest House III	1F電梯旁 Next to the elevator	<1	113/12/11	
13	綜二大樓電子所 General Building II : Institute of Electronics Engineering	3F廁所旁 Next To The Restroom (220V)	<1	113/12/11	
14	綜二大樓語言中心 General Building II : Center for Language Education	1F教授休息室 Faculty Lounge	<1	113/12/11	
15	資電館資工系 Electrical Engineering and Computer Science Building : Department of Computer Science	220室 Room220	4	113/12/11	
16	行政大樓 Administration Building	1F168教室 Room168	<1	113/12/11	
17	行政大樓 Administration Building	3F校園規劃室前左 On the left in front of the Division of Campus Planning	<1	113/12/11	
18	行政大樓 Administration Building	3F學務長室旁左 On the left next to the Dean Office of Student Affairs	2	113/12/11	
19	化工館 Department of Chemical Engineering	112室 Room112	<1	113/12/11	
20	台達館電機系 Delta Hall : Department of Electrical Engineering	8F-813室對面 Opposite to Room 813	<1	113/12/11	
21	台達館電機系 Delta Hall : Department of Electrical Engineering	9F-茶水間 Pantry Room	<1	113/12/11	
22	生物科技館 Biological Science Technology Building	116室 Room116	5	113/12/11	
23	新齋 (Dorm Hsin)	3樓洗衣間旁 (Next to the laundry room on the 3rd floor)	<1	113/12/11	
24	清齋 (Dorm Tsing)	AB棟 (Building AB) 5樓電梯前 (In front of the elevator on the 5th floor)	<1	113/12/11	
25	清齋 (Dorm Tsing)	DE棟 (Building DE) 6樓電梯前 (In front of the elevator on the 6th floor)	<1	113/12/11	

符合規定 in compliance with regulations



26	仁齋(Dorm Jen)		4樓412旁(Next to 412 on the 4th floor)	<1	113/12/11
27	鴻齋(Dorm Jen)		6樓洗衣間(Laundry room on the 6th floor)	<1	113/12/11
28	文齋(Dorm Wen)		5樓502(502, 5th floor)	<1	113/12/11
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	綜合教學大樓-9F-茶水間(招待所) General Education Building-9F-Tea Room		<1	113/12/11	符合規定 in compliance with regulations
2	體健大樓-4F-廁所旁 Health and Physical Education Building-4F-beside toilet		<1	113/12/11	
3	推廣教育大樓-2F-9213室 Extended Education Building-2F-9213 Room		<1	113/12/11	
4	推廣教育大樓-4F-9412室(數理所辦公室) Extended Education Building-4F-9412 Room (office for Graduate Institute of Mathematics and Science Education)		<1	113/12/11	
5	竹師攬星樓-1F-(校外宿舍) National Hsinchu University of Education Lan Xing Building-1F		<1	113/12/11	
6	樹德樓-5F-洗衣機旁 Shu Te Dorm-5F-beside washing machine		<1	113/12/11	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)

