

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	工料館 Engineering and System Science Building	5F ESS 524W	<1	114/9/10	符合規定 in compliance with regulations
2	綜二大樓計算機中心 General Building II : Computer and Communication Center	314室 Room314	<1	114/9/10	
3	綜三大樓數學系 General Building III : Department of	200室 Room200	<1	114/9/10	
4	資電館資工系 Electrical Engineering and Computer Science Building : Department of Computer Science	431室 Room431	<1	114/9/10	
5	資電館電機系 Electrical Engineering and Computer Science Building : Department of Electrical Engineering	724室 Room724	<1	114/9/10	
6	體育館 Education Building	119室右 Room119 Left	<1	114/9/10	
7	游泳池 Swimming Pool	入口旁 Beside the entrance	<1	114/9/10	
8	司令台 Ceremonial Stand	地下室 Basement	<1	114/9/10	
9	材料實驗館 Materials Science Laboratory	109室 Room109	<1	114/9/10	
10	清華會館 Guest House I	1F	<1	114/9/10	
11	清華會館 Guest House I	3F	<1	114/9/10	
12	行政大樓 Administration Building	2F保管組旁 Next to the Division of Property Management	<1	114/9/10	
13	行政大樓 Administration Building	2F遠距教室旁 Next to the distance learning classroom	<1	114/9/10	
14	化工館 Department of Chemical Engineering	106室 Room106	<1	114/9/10	
15	旺宏館國際會議廳 Macronix Building : International	1F茶水間 Pantry Room	<1	114/9/10	
16	旺宏館國際會議廳 Macronix Building : International	3F茶水間 Pantry Room	<1	114/9/10	
17	工程一館工工系 Engineering Building I : Department of Industrial Engineering and Engineering Management	8F	<1	114/9/10	
18	新齋(Dorm Cheng)	B棟(Building B) 8樓 (8th floor)	<1	114/9/10	
19	明齋(Dorm Ming)	2樓浴室 (2nd floor bathroom)	<1	114/9/10	
20	學齋(Dorm Shue)	A棟(Building A) 6樓(6th floor)	<1	114/9/10	
21	清齋(Dorm Tsing)	B棟(Building B) 6樓洗衣間(Laundry room on the sixth	<1	114/9/10	
22	清齋(Dorm Tsing)	DE棟(Building DE) 7樓電梯前旁(In front of the elevator on the seventh floor)	<1	114/9/10	
23	清齋(Dorm Tsing)	AB棟(Building AB) 流理臺旁(Next to the kitchen sink)	<1	114/9/10	
24	禮齋(Dorm Li)	2樓220(Room 220 on the 2nd floor)	<1	114/9/10	
25	碩齋(Dorm Shuo)	1樓136旁(Next to Room 136, 1st Floor)	<1	114/9/10	
26	文齋(Dorm Wen)	2樓218(Room 218, 2nd Floor)	<1	114/9/10	
	以下空白				

註1. 飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大略521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	圖書館(南大分館)-3F-電梯旁 Library Nanda Branch-3F-beside elevator		<1	114/9/10	符合規定 in compliance with regulations
2	警衛室-1F-值班室旁 Nanda Campus Guard room-1F		<1	114/9/10	
3	學生第二活動中心-3F Student Activity Center II-3F		<1	114/9/10	
4	音樂二館-5F Music Building II-5F		<1	114/9/10	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)

