

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	資電館資工系 Electrical Engineering and Computer Science Building : Department of Computer Science	大廳 Lobby	<1	113/3/13	符合規定 in compliance with regulations
2	資電館資工系 Electrical Engineering and Computer Science Building : Department of Computer Science	435室 Room435	<1	113/3/13	
3	清華實驗室(220V) Tsing Hua Laboratory(220V)	4F茶水間 Pantry Room	<1	113/3/13	
4	綜二大樓8F會議廳 General Building II : 8F Conference Hall	交誼廳 Common area	<1	113/3/13	
5	自強樓 Tzi Chiang Faculty Residences	2F	<1	113/3/13	
6	男單宿舍 Men's Single Dormitory	2F	<1	113/3/13	
7	行政大樓 Administration Building	1F(人事室前 In front of the Office of Personnel)	<1	113/3/13	
8	行政大樓 Administration Building	4F營繕組 Divison of Construction & Maintenance	<1	113/3/13	
9	行政大樓 Administration Building	2F第一會議室 Administration building Conference Room I	<1	113/3/13	
10	工程一館動機館 Engineering Building I : Department of Power Mechanical Engineering	429室 Room429	<1	113/3/13	
11	工程一館動機館 Engineering Building I : Department of Power Mechanical Engineering	601室 Room601	<1	113/3/13	
12	科儀館 Scientific Instrument Center	3F	<1	113/3/13	
13	化工館 Department of Chemical Engineering	321室 Room321	<1	113/3/13	
14	動化館 Chemistry and Power Mechanical Engineering Building	1F	<1	113/3/13	
15	化學館 Department of Chemistry	2F	<1	113/3/13	
16	義齋(Dorm Yi)	301旁 (Next to 301 on the 3rd floor)	<1	113/3/13	
17	鴻齋(Dorm Hsin)	3樓洗衣間(Laundry room on the 3rd floor)	<1	113/3/13	
18	學齋(Dorm Shiue)	C棟(Building C) 1樓104(1st floor 104)	<1	113/3/13	
19	清齋(Dorm Tsing)	DE棟(Building AB) 2樓電梯前(In front of the elevator on the 2nd floor	<1	113/3/13	
20	信齋(Dorm Shinn)	B棟(Building B) 2樓浴室(2nd floor bathroom)	<1	113/3/13	
21	儒齋(Dorm Ru)	C棟(Building C)1樓 (1st floor)	<1	113/3/13	
22	儒齋(Dorm Ru)	A棟(Building C)3樓 (3rd floor)	<1	113/3/13	
23	實齋(Dorm Shyr)	2樓浴室東(The second-floor bathroom east)	<1	113/3/13	
24	碩齋(Dorm Shuo)	5樓502旁(Next to 502 on the 5th floor)	<1	113/3/13	
25	雅齋(Dorm Ya)	3樓328(3F328)	<1	113/3/13	
	以下空白				



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	鳴鳳樓-2F-洗手間旁 Ming Feng Dorm-2F-beside toilet		<1	113/3/13	符合規定 in compliance with regulations
2	崇善樓-5F-洗手間旁 Chung Shan Dorm-5F-beside toilet		<1	113/3/13	
3	迎曦軒-3F-後棟樓梯旁 Ying His Dorm-3F-the back building beside stairway		<1	113/3/13	
4	樹德樓-3F-洗衣機旁 Shu Te Dorm-3F-beside washing machine		<1	113/3/13	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)

