


國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	台達館材料系 Delta Hall : Department of Materials Science	4F-410室 Room410	<1	113/10/9	符合規定 in compliance with regulations
2	台達館電機系 Delta Hall : Department of Electrical	2F-茶水間 Pantry Room	<1	113/10/9	
3	台達館電機系 Delta Hall : Department of Electrical	8F-853室對面 Opposite to Room 853	<1	113/10/9	
4	台達館資工系 Delta Hall : Department of Computer Science	7F-靠籃球場窗戶邊 Near the window of the basketball	<1	113/10/9	
5	台達館奈微所 Delta Hall : Institute of NanoEngineering and MicroSystems	3F-323室 Room323	<1	113/10/9	
6	資電館電機系 Electrical Engineering and Computer Science Building : Department of Electrical Engineering	一樓管理員室前 1F In front of the administrator's office	<1	113/10/9	
7	材料科技館 Materials Science & Technology Building	202室 Room202	<1	113/10/9	
8	旺宏館圖書館 Macronix Building : Library	4F K書中心 Study Room(左 Left side)	<1	113/10/9	
9	工程一館動機館 Engineering Building I : Department of Power Mechanical Engineering	501室 Room501	<1	113/10/9	
10	綜三大樓數學系 General Building III : Department of	100室 Room100	<1	113/10/9	
11	綜二大樓計算機中心 General Building II : Computer and Communication Center	211室 Room211	<1	113/10/9	
12	蒙民偉樓 Mong Man Wai Building	3F	<1	113/10/9	
13	學士後醫系 School of Post-Baccalaureate Medicine	生物科技館2F Biological Science Technology Building	<1	113/10/9	
14	人文社會學院 College of Humanities and Social Sciences	C633	<1	113/10/9	
15	人文社會學院 College of Humanities and Social Sciences	C416教授休息室 Faculty Lounge	<1	113/10/9	
16	平齋(Dorm Ping)	2樓浴室(2nd floor bathroom)	<1	113/10/9	
17	清齋(Dorm Tsing)	AB棟(Building AB) 4樓電梯前(In front of the elevator on the 4th floor)	<1	113/10/9	
18	清齋(Dorm Tsing)	DE棟(Building DE) 3樓電梯前(In front of the elevator on the 3rd floor)	<1	113/10/9	
19	禮齋(Dorm Li)	3樓319(Next to 319, 3rd floor)	<1	113/10/9	
20	鴻齋(Dorm Jen)	4樓洗衣間(Laundry room on the 4th floor)	<1	113/10/9	
21	實齋(Dorm Shinn)	1樓交誼廳(1st Floor Friendship Hall)	<1	113/10/9	
22	學齋(Dorm Shiue)	D棟(Building A) 4樓(4th floor)	<1	113/10/9	
23	儒齋(Dorm Ru)	D棟(Building D) 4樓(4th floor)	<1	113/10/9	
24	雅齋(Dorm Ya)	2樓210旁(Next to 210, 2nd floor)	<1	113/10/9	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	行政大樓-4F-右側洗手間旁 Administration Building-4F-beside right toilet		<1	113/10/9	符合規定 in compliance with regulations
2	學生第一活動中心-4F-洗手間旁 Student Activity Center I-4F-beside toilet		<1	113/10/9	
3	體健大樓-4F-405室旁 Health and Physical Education Building-4F-beside 405 Room		<1	113/10/9	
4	推廣教育大樓-6F-前端洗手間旁 Extended Education Building-6F-beside front toilet		<1	113/10/9	
5	推廣教育大樓-3F-電梯旁 Extended Education Building-3F-beside elevator		<1	113/10/9	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)

