


國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	生命科學一館 Life Science Building I	515室 Room515	<1	114/2/12	
2	生命科學二館 Life Science Building II	323室 Room323	<1	114/2/12	
3	人文社會學院 College of Humanities and Social Sciences	A202	<1	114/2/12	
4	人文社會學院 College of Humanities and Social Sciences	C205	<1	114/2/12	
5	台積館 TSMC Building	四樓茶水間 4F Pantry Room	<1	114/2/12	
6	生醫科學系 Department of Biomedical Engineering & Environmental Sciences	304室 Room304	<1	114/2/12	
7	工科新館 Engineering and System Science New Building	2F	<1	114/2/12	
8	綠能教學大樓 Green Energy Research and Education Building (Lee Tsen Min Building)	2F茶水間 Pantry Room	<1	114/2/12	
9	教育館 Education Building	1F茶水間 Pantry Room	<1	114/2/12	
10	教育館 Education Building	214	<1	114/2/12	
11	化工館 Department of Chemical Engineering	B1	<1	114/2/12	
12	外工班 Outside Work Class	茶水間 Pantry Room	<1	114/2/12	
13	化學館 Department of Chemistry	1F112教授休息室 Room112 (Faculty Lounge)	<1	114/2/12	
14	旺宏圖書館 Macronix Building : Library	1F公務區 Official Area	<1	114/2/12	
15	育成中心 Center of Incubator	7F	<1	114/2/12	
16	華齋 (Dorm Hua)	304對面 (Opposite 304)	<1	114/2/12	
17	新齋 (Dorm Hsing)	4樓B406對面 (Opposite B406 on the 4th floor)	<1	114/2/12	
18	學齋 (Dorm Shiuie)	C棟 (Building C) 3樓 (3rd floor)	<1	114/2/12	
19	學齋 (Dorm Shiuie)	B棟 (Building B) 6樓 (6th floor)	<1	114/2/12	
20	清齋 (Dorm Tsing)	B棟 (Building B) 4樓洗衣間 (Laundry room on the 4th floor)	<1	114/2/12	
21	儒齋 (Dorm Ru)	A棟 (Building A) 6樓412旁 (6th floor)	<1	114/2/12	
22	碩齋 (Dorm Shuo)	3樓302旁 (Next to 302 on the 3rd floor)	<1	114/2/12	
23	信齋 (Dorm Shinn)	B棟 (Building B) 4樓浴室 (4th floor bathroom)	<1	114/2/12	
24	雅齋 (Dorm Wen)	1樓106 (1st floor 106)	<1	114/2/12	
	以下空白				

符合規定 in compliance with regulations



註1. 飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	行政大樓-1F-茶水間 Administration Building-1F-Pantry Room of General Affair		<1	114/2/12	符合規定 in compliance with regulations
2	綜合教學大樓-4F-前庭茶水間 General Education Building-4F-the front tea room		<1	114/2/12	
3	鳴鳳樓-3F-洗手間旁 Ming Feng Dorm-3F-beside toilet		<1	114/2/12	
4	崇善樓-3F-洗手間旁(力霸) Chung Shan Dorm-3F-beside toilet		<1	114/2/12	
	以下空白				

註1. 飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)

