


國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	生命科學二館 Life Science Building II	412室內 Inside Room412	<1	114/3/6	符合規定 in compliance with regulations
2	人文圖書館 Humanities Library	2F	<1	114/3/6	
3	人文社會學院 College of Humanities and Social Sciences	C307	<1	114/3/6	
4	台積館 TSMC Building	二樓廁所旁 2F Next To The Restroom	<1	114/3/6	
5	生醫科學系 Department of Biomedical Engineering & Environmental Sciences	604室 Room604	<1	114/3/6	
6	工科新館 Engineering and System Science New Building	1F	<1	114/3/6	
7	工科新館 Engineering and System Science New Building	5F	<1	114/3/6	
8	綜二大樓電通中心 Computer and Communication Research	710室 Room710	<1	114/3/6	
9	綜二大樓8F技科所 General Building II : Institute of Computational and Modeling Science	茶水間 Pantry Room	<1	114/3/6	
10	綜三館統計所 General Building III : Institute of Statistics	8F教職員休息室 Faculty Lounge	<1	114/3/6	
11	台達館資工系 Delta Hall : Department of Computer Science	5F-520室 Room520	<1	114/3/6	
12	旺宏館圖書館 Macronix Building : Library	1F讀者區廁所旁 Next to the restroom in the readers area	<1	114/3/6	
13	旺宏館圖書館 Macronix Building : Library	5F讀者區廁所旁 Readers Area (Next To The Restroom)	<1	114/3/6	
14	新齋(Dorm Hsing)	6樓B606對面(Opposite B606 on the 6th floor)	<1	114/3/6	
15	新齋(Dorm Hsing)	1樓洗衣間旁(Next to the laundry room on the first floor)	<1	114/3/6	
16	學齋(Dorm Shiue)	C棟(Building C) 4樓(4th floor)	<1	114/3/6	
17	儒齋(Dorm Ru)	B棟(Building B) 4樓(4th floor)	<1	114/3/6	
18	清齋(Dorm Tsing)	DE棟(Building DE) 4樓電梯前(In front of the elevator on the 4th floor)	<1	114/3/6	
19	清齋(Dorm Tsing)	D棟(Building D) 10樓洗衣間(Laundry room on the 10th fl	<1	114/3/6	
20	碩齋(Dorm Shuo)	3樓336旁(Next to 336 on the 3rd floor)	<1	114/3/6	
21	信齋(Dorm Shinn)	A棟(Building A) 5樓浴室(5th floor bathroom)	<1	114/3/6	
22	文齋(Dorm Wen)	5樓 (5th floor)	<1	114/3/6	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	學生第一活動中心-2F-茶水間 Student Activity Center I-2F-Tea Room		<1	114/3/6	符合規定 in compliance with regulations
2	體育館-1F Physical Education Hall-1F		<1	114/3/6	
3	學生第二活動中心-2F Student Activity Center II-2F		<1	114/3/6	
4	音樂館-1F-走廊 Music Building-1F-corridor		<1	114/3/6	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)

