


國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	清華實驗室(220V) Tsing Hua Laboratory(220V)	1F茶水間 Pantry Room	<1	114/11/5	符合規定 in compliance with regulations
2	原子爐 Nuclear Reactor Building	1F應變中心 Emergency operations center	<1	114/11/5	
3	資電館電機系 Electrical Engineering and Computer Science Building : Department of Electrical Engineering	211室 Room211	<1	114/11/5	
4	資電館電機系 Electrical Engineering and Computer Science Building : Department of Electrical Engineering	824室 Room824	<1	114/11/5	
5	工程一館動機館 Engineering Building I : Department of Power Mechanical Engineering	201室 Room201	<1	114/11/5	
6	化工館 Department of Chemical Engineering	216室 Room216	<1	114/11/5	
7	動化館 Chemistry and Power Mechanical Engineering Building	214室 Room214	<1	114/11/5	
8	化學館 Department of Chemistry	4F	<1	114/11/5	
9	化學館 Department of Chemistry	7F	<1	114/11/5	
10	台積館 TSMC Building	9F茶水間 Pantry Room	<1	114/11/5	
11	教育館 Education Building	3F管理員室 Administrator's Office	<1	114/11/5	
12	文學館 Museum of Literature	2F	<1	114/11/5	
13	清齋(Dorm Tsing)	7樓洗衣間 (7th Floor Laundry Room)	<1	114/11/5	
14	新齋(Dorm Hsin)	8樓B806對面(Opposite B806 on the 8th floor)	<1	114/11/5	
15	實齋(Dorm Shyr)	3樓浴室西(3rd Floor Bathroom West)	<1	114/11/5	
16	信齋(Dorm Shinn)	C棟(Building C) 3樓浴室 (3rd floor bathroom)	<1	114/11/5	
17	儒齋(Dorm Ru)	B棟(Building B) 6樓(6th floor)	<1	114/11/5	
18	儒齋(Dorm Ru)	D棟(Building D) 6樓(6th floor)	<1	114/11/5	
19	雅齋(Dorm Ya)	5樓505旁 (Next to Room 505 on the fifth floor)	<1	114/11/5	
20	文齋(Dorm Wen)	5樓522旁 (Next to Room 522 on the fifth floor)	<1	114/11/5	
21	慧齋(Dorm Hwei)	一樓交誼廳(First floor lounge)	<1	114/11/5	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL.)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	藝設系大樓-4F-電梯邊 Art and Design Building-4F-beside elevator		<1	114/11/5	符合規定 in compliance with regulations
2	推廣教育大樓-3F-後端洗手間旁 Extended Education Building-3F-beside back toilet		<1	114/11/5	
3	南苑招待所-1F Nanyuan Guest House-1F		<1	114/11/5	
4	崇善樓-4F-洗手間旁 Chung Shan Dorm-4F-beside toilet		<1	114/11/5	
5	迎曦軒-2F-後棟樓梯旁 Ying His Dorm-2F-the back building beside stairway		<1	114/11/5	
	以下空白				

註1. 飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)

