

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	台積電 TSMC Building	三樓茶水間 3F Pantry Room	<1	114/4/9	符合規定 in compliance with regulations
2	工科館 Engineering and System Science Building	501E	<1	114/4/9	
3	綜二大樓電通中心 Computer and Communication Research	743室 Room743	<1	114/4/9	
4	綜二大樓教務處 General Building II : Office of Academic Affairs	2F茶水間 Pantry Room	<1	114/4/9	
5	綜二大樓學科所 General Building II : Institute of Learning Sciences and Technologies	4F茶水間 Pantry Room	<1	114/4/9	
6	綜三大樓數學系 General Building III : Department of	302室 Room302	<1	114/4/9	
7	綜三大樓普物教室 General Building III : General Physics	201室 Room201	<1	114/4/9	
8	物理館 Physics Building	5F(511旁 Next to the room511)	<1	114/4/9	
9	工程三館 Engineering Building III	108室 Room108	<1	114/4/9	
10	材料科技館 Materials Science & Technology Building	301室 Room301	<1	114/4/9	
11	資電館資工系 Electrical Engineering and Computer Science Building : Department of Computer Science	531室 Room531	<1	114/4/9	
12	教育館 Education Building	217	<1	114/4/9	
13	校友體育館 Alumni Gymnasium	2F	<1	114/4/9	
14	綜四館經管組 General Building IV : Division of Dining and Facilities Management	201(左 Left side)	<1	114/4/9	
15	旺宏館圖書館 Macronix Building : Library	3F讀者區廁所旁 Next to the restroom in the readers area	<1	114/4/9	
16	旺宏館圖書館 Macronix Building : Library	5F讀者區茶水間 Readers Area (Pantry Room)	<1	114/4/9	
17	誠齋(Dorm cheng)	1樓樓梯西(Ground floor staircase west)	<1	114/4/9	
18	新齋(Dorm Hsing)	8樓B811對面(Opposite to 811 on the 8th floor)	<1	114/4/9	
19	學齋(Dorm Shiue)	C棟(Building C) 5樓(5th floor)	<1	114/4/9	
20	學齋(Dorm Shiue)	D棟(Building B) 5樓(5th floor)	<1	114/4/9	
21	清齋(Dorm Tsing)	DE棟(Building DE) 8樓電梯前(In front of the elevator on the 8th floor)	<1	114/4/9	
22	清齋(Dorm Tsing)	D棟(Building D) 3樓洗衣間(Laundry room on the third	<1	114/4/9	
23	碩齋(Dorm Shuo)	4樓402旁(Next to 402 on the 4th floor)	<1	114/4/9	
24	儒齋(Dorm Ru)	D棟(Building D) 2樓(Second floor)	<1	114/4/9	
25	靜齋(Dorm Jing)	2樓207 (Next to 207 on the second floor)	<1	114/4/9	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	體健大樓-5F-504室旁 Health and Physical Education Building-5F-beside 504 Room		<1	114/4/9	符合規定 in compliance with regulations
2	音樂二館-3F Music Building II-3F		<1	114/4/9	
3	迎曦軒-1F-後棟樓梯旁(力霸) Ying His Dorm-1F-the back building beside stairway		<1	114/4/9	
4	樹德樓-2F-212室旁(力霸) Shu Te Dorm-2F-beside 212 Room		<1	114/4/9	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)

