

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	生命科學一館 Life Science Building I	213室 Room213	<1	115/3/4	符合規定 in compliance with regulations
2	清華實驗室(220V) Tsing Hua Laboratory	4F茶水間 Pantry Room	<1	115/3/4	
3	綜二大樓8F會議廳 General Building II : 8F Conference Hall	交誼廳 Common area	<1	115/3/4	
4	資電館資工系 Electrical Engineering and Computer Science Building : Department of Computer Science	大廳 Lobby	<1	115/3/4	
5	資電館資工系 Electrical Engineering and Computer Science Building : Department of Computer Science	435室 Room435	<1	115/3/4	
6	自強樓 Tzi Chiang Faculty Residences	2F	<1	115/3/4	
7	男單宿舍 Men's Single Dormitory	2F	<1	115/3/4	
8	行政大樓 Administration Building	1F(人事室前 In front of the Office of Personnel)	<1	115/3/4	
9	行政大樓 Administration Building	4F營繕組 Divison of Construction & Maintenance	<1	115/3/4	
10	行政大樓 Administration Building	2F第一會議室 Administration building Conference Room I	<1	115/3/4	
11	工程一館動機館 Engineering Building I : Department of Power Mechanical Engineering	429室 Room429	<1	115/3/4	
12	工程一館動機館 Engineering Building I : Department of Power Mechanical Engineering	601室 Room601	<1	115/3/4	
13	科儀館 Scientific Instrument Center	3F	<1	115/3/4	
14	化工館 Department of Chemical Engineering	321室 Room321	<1	115/3/4	
15	動化館 Chemistry and Power Mechanical Engineering Building	1F	<1	115/3/4	
16	化學館 Department of Chemistry	2F	<1	115/3/4	
17	義齋(Dorm Yi)	2樓301旁(Next to Room 301 on the second floor)	<1	115/3/4	
18	平齋(Dorm Ping)	1樓浴室(First floor bathroom)	<1	115/3/4	
19	新齋(Dorm Hsing)	5樓A區(5th Floor, Area A)	<1	115/3/4	
20	學齋(Dorm Shiue)	A棟(Building A) 1樓(First floor)	<1	115/3/4	
21	清齋(Dorm Tsing)	B棟(Building B) 7樓洗衣間(7th Floor Laundry Room)	<1	115/3/4	
22	禮齋(Dorm Li)	1樓102旁 (Next to 102 on the 1st floor)	<1	115/3/4	
23	鴻齋(Dorm Hung)	3樓洗衣間(3rd Floor Laundry Room)	<1	115/3/4	
24	仁齋(Dorm Jen)	1樓交誼廳(1st Floor Lounge)	<1	115/3/4	
25	儒齋(Dorm RU)	C棟(Building C) 4樓(4th floor)	<1	115/3/4	
	以下空白		<1	115/3/4	

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	鳴鳳樓-2F-洗手間旁 Ming Feng Dorm-2F-beside toilet		<1	115/3/4	符合規定 in compliance with regulations
2	崇善樓-5F-洗手間旁 Chung Shan Dorm-5F-beside toilet		<1	115/3/4	
3	迎曦軒-3F-後棟樓梯旁 Ying His Dorm-3F-the back building beside stairway		<1	115/3/4	
4	樹德樓-3F-洗衣機旁 Shu Te Dorm-3F-beside washing machine		<1	115/3/4	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)

