

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	綜二大樓奈微所 General Building II : Institute of NanoEngineering and MicroSystems	8F茶水間 Pantry Room	<1	113/6/5	符合規定 in compliance with regulations
2	綜三大樓理學院 General Building III : College of Science	地下室 Basement	<1	113/6/5	
3	體育館 Education Building	107室 Room107	<1	113/6/5	
4	台達館材料系 Delta Hall : Department of Materials Science and Engineering	B1-111休息室 111 Lounge	<1	113/6/5	
5	台達館資工系 Delta Hall : Department of Computer Science	6F-茶水間 Pantry Room	<1	113/6/5	
6	台達館奈微所 Delta Hall : Institute of NanoEngineering and MicroSystems	3F-茶水間 Pantry Room	<1	113/6/5	
7	化工館 Department of Chemical Engineering	521室 Room521	<1	113/6/5	
8	化學館 Department of Chemistry	6F	<1	113/6/5	
9	大門口 Main Gate	收費亭 Toll Station	<1	113/6/5	
10	工程一館動機館 Engineering Building 1 : Department of Power Mechanical Engineering	301室 Room301	<1	113/6/5	
11	清華會館 Guest House I	8F	<1	113/6/5	
12	綠能教學大樓 Green Energy Research and Education Building (Lee Tsen Min Building)	4F茶水間 Pantry Room	<1	113/6/5	
13	清華實驗室(220V) Tsing Hua Laboratory(220V)	8F茶水間 Pantry Room	<1	113/6/5	
14	明齋(Dorm Ming)	3樓浴室(3rd floor bathroom)	<1	113/6/5	
15	學齋(Dorm Shiue)	D棟(Building D) 3樓 (6th floor)	<1	113/6/5	
16	清齋(Dorm Tsing)	DE棟(Building DE) 10樓電梯前(7th floor laundry)	<1	113/6/5	
17	文齋(Dorm Wen)	3樓322(322, 3rd floor)	<1	113/6/5	
18	靜齋(Dorm Ru)	3樓315(315, 3rd floor)	<1	113/6/5	
19	慧齋(Dorm Huei)	一樓交誼廳(1st floor social hall)	<1	113/6/5	
20	雅齋(Dorm Ya)	4樓425(425, 4th floor)	<1	113/6/5	
21	信齋(Dorm Hung)	C棟(Building C) 2樓浴室 (2nd floor bathroom)	<1	113/6/5	
22	仁齋(Dorm Jen)	3樓312旁(Next to 312 on the 3rd floor )	<1	113/6/5	
	以下空白				



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	行政大樓-1F-教務處辦公室 Administration Building-1F-Office of Academic Affair		<1	113/6/5	符合規定 in compliance with regulations
2	綜合教學大樓-2F-前端茶水間 General Education Building-2F-the front tea room		<1	113/6/5	
3	教學大樓-1F-圖說資料室 Education Building-1F-Data base		<1	113/6/5	
4	數理教育大樓-4F-右側樓梯間 Mathematics and Science Education Building-4F-the right staircase		<1	113/6/5	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards  
大腸桿菌群 Coliform : 6 (CFU/100mL)

