


國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	人文社會學院 College of Humanities and Social Sciences	C416教授休息室 Faculty Lounge	<1	115/10/14	符合規定 in compliance with regulations
2	人文社會學院 College of Humanities and Social Sciences	C633	<1	115/10/14	
3	學士後醫系 School of Post-Baccalaureate Medicine	生物科技館2F Biological Science Technology Building 2F	<1	115/10/14	
4	教育大樓 College of Education Building	759室 Room 759	<1	115/10/14	
5	蒙民偉樓 Mong Man Wai Building	3F	<1	115/10/14	
6	綜二大樓計算機中心 General Building II: Computer and Communication Center	211室 Room 211	<1	115/10/14	
7	綜三大樓數學系 General Building II: Department of Mathematics	100室 Room 100	<1	115/10/14	
8	材料科技館 Materials Science & Technology Building	202室 Room 202	<1	115/10/14	
9	資電館電機系 Electrical Engineering and Computer Science Building: Department of Electrical Engineering	一樓管理員室前 1F In front of the administrator's office	<1	115/10/14	
10	工程一館動機館 Engineering Building I: Department of Power Mechanical	501室 Room 501	<1	115/10/14	
11	台達館電機系 Delta Hall: Department of Electrical Engineering	2F-茶水間 Pantry Room	<1	115/10/14	
12	台達館奈微所 Delta Hall: Institute of NanoEngineering and MicroSystems	3F-323室 Room 323	<1	115/10/14	
13	台達館材料系 Delta Hall: Department of Materials Science and Engineering	4F-410室 Room 410	<1	115/10/14	
14	台達館資工系 Delta Hall: Department of Computer Science	7F-靠籃球場窗戶邊 Near the window of the basketball	<1	115/10/14	
15	台達館電機系 Delta Hall: Department of Electrical Engineering	8F-853室對面 Opposite to Room 853	<1	115/10/14	
16	平齋(Dorm Pin)	2樓浴室(Second floor bathroom)	<1	115/10/14	
17	新齋(Dorm Hsin)	5樓教官室旁 (Next to the instructor's office on the fifth	<1	115/10/14	
18	學齋(Dorm Shiu)	D棟(Building D) 4樓(4th floor)	<1	115/10/14	
19	學齋(Dorm Shiu)	D棟(Building D) 6樓(6th floor)	<1	115/10/14	
20	禮齋(Dorm Li)	3樓319 (1st floor bathroom)	<1	115/10/14	
21	鴻齋(Dorm Jing)	4樓洗衣間 (Next to the bathroom)	<1	115/10/14	
22	仁齋(Dorm Jen)	4樓401旁 (Next to 401 on the 4th floor)	<1	115/10/14	
23	實齋(Dorm Shyr)	1樓交誼廳(First-floor lounge)	<1	115/10/14	
24	信齋(Dorm Shinn)	B棟(Building B) 3樓浴室 (Third floor bathroom)	<1	115/10/14	
25	信齋(Dorm Shinn)	C棟(Building C) 5樓浴室 (Fifth floor bathroom)	<1	115/10/14	
26	儒齋(Dorm Ru)	B棟(Building B) 3樓(Third floor)	<1	115/10/14	
27	儒齋(Dorm Ru)	B棟(Building B) 5樓(Fifth floor)	<1	115/10/14	
28	儒齋(Dorm Ru)	C棟(Building C) 5樓(Fifth floor)	<1	115/10/14	
29	儒齋(Dorm Ru)	D棟(Building D) 3樓(Third floor)	<1	115/10/14	
30	雅齋(Dorm Ya)	1樓122 (1st floor, 122)	<1	115/10/14	
31	文齋(Dorm Wen)	3樓322 (3rd Floor, 322)	<1	115/10/14	
32	靜齋(Dorm Jing)	2樓廚房(2nd floor kitchen)	<1	115/10/14	
33	慧齋(Dorm Hwei)	1樓廚房(1st floor kitchen)	<1	115/10/14	
	以下空白				

註1. 飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	綜合教學大樓-8F-茶水間 General Education Building-8F-Tea Room		<1	115/10/14	符合規定 in compliance with regulations
2	學生第一活動中心-3F-洗手間旁 Student Activity Center 1-3F-beside toilet		<1	115/10/14	
3	推廣教育大樓-3F-電梯旁 Extended Education Building-3F-beside elevator		<1	115/10/14	
4	竹師攬星樓-1F-(校外宿舍) National Hsinchu University of Education Lan Xing Building-1F		<1	115/10/14	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)

