

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	人文圖書館 Humanities Library	1F	<1	114/6/4	符合規定 in compliance with regulations
2	人文社會學院 College of Humanities and Social Sciences	B304	<1	114/6/4	
3	台積館 TSMC Building	四樓廁所旁 4F Next To The Restroom	<1	114/6/4	
4	台積館 TSMC Building	六樓廁所旁 6F Next To The Restroom	<1	114/6/4	
5	台積館 TSMC Building	八樓茶水間 8F Pantry Room	<1	114/6/4	
6	生醫科學系 Department of Biomedical Engineering & Environmental Sciences	203室 Room203	<1	114/6/4	
7	生醫科學系 Department of Biomedical Engineering & Environmental Sciences	704室 Room704	<1	114/6/4	
8	工科新館 Engineering and System Science New Building	6F	<1	114/6/4	
9	綜三大樓數學系 General Building III : Department of Statistics	610室 Room610	<1	114/6/4	
10	綜三館統計所 General Building III : Institute of Statistics	637室 Room637	<1	114/6/4	
11	教育館 Education Building	3F(靠近復興中學 Close to Kuang-Fu High School)	<1	114/6/4	
12	旺宏館圖書館 Macronix Building : Library	2F讀者區茶水間 Pantry (in readers area)	<1	114/6/4	
13	旺宏館圖書館 Macronix Building : Library	3F公務區 Official Area	<1	114/6/4	
14	旺宏館全球處 Macronix Building : Office of Global Affairs	1F茶水間 Pantry Room	<1	114/6/4	
15	旺宏館行政中樞 Macronix Building : Administrative Center	7F茶水間 Pantry Room (校長室 Office of the President)	<1	114/6/4	
16	誠齋(Dorm Hua)	2樓電梯東(Elevator East on the 2nd floor)	<1	114/6/4	
17	清齋(Dorm Tsing)	D棟(Building D) 6樓洗衣間(Laundry Room on the 6th Floor of Building D)	<1	114/6/4	
18	學齋(Dorm Shiu)	A棟(Building A) 7樓(7th floor)	<1	114/6/4	
19	清齋(Dorm Tsing)	B棟(Building B) 5樓洗衣間(Laundry Room on the 5th Floor of Building B)	<1	114/6/4	
20	清齋(Dorm Tsing)	AB棟(Building AB) 6樓電梯前(In front of the elevator on the 6th floor)	<1	114/6/4	
21	儒齋(Dorm Ru)	D棟(Building D) 1樓(1st floor)	<1	114/6/4	
22	禮齋(Dorm Li)	3樓302旁(Next to 302 on the 3rd floor)	<1	114/6/4	
23	信齋(Dorm Shinn)	B棟(Building B) 1樓浴室(1st floor bathroom)	<1	114/6/4	
24	文齋(Dorm Wen)	2樓202(Room 202, 2nd Floor)	<1	114/6/4	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大馬路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	綜合教學大樓-1F-後端茶水間 General Education Building-1F-the back tea room		<1	114/6/4	符合規定 in compliance with regulations
2	教學大樓-2F-中央樓梯間 Education Building-2F-center staircase		<1	114/6/4	
3	藝設系大樓-3F-樓梯邊 Art and Design Building-3F-beside elevator		<1	114/6/4	
4	學生活動中心-1F-入口左側 Student Activity Center 1-1F-left entrance		<1	114/6/4	
	以下空白				

註1. 飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)

