


國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City					
1	育成中心政經學院 Incubation Center School of Political Science	2F 靠機房茶水間 2F Pantry Room next to the Machine	<1	114/10/8	符合規定 in compliance with regulations
2	資電館資工系 Electrical Engineering and Computer Science Building : Department of Computer Science	830 室 Room 830	<1	114/10/8	
3	資電館電機系 Electrical Engineering and Computer Science Building : Department of Electrical Engineering	313 室 Room 313	<1	114/10/8	
4	教育館 Education Building	2F 辦公室 Office	<1	114/10/8	
5	體育館 Education Building	119 室左 Room 119 Left	<1	114/10/8	
6	第二招待所 Guest House II	1F 餐廳 Restaurant	<1	114/10/8	
7	行政大樓 Administration Building	2F 保管組旁 Next to the Division of Property Management	<1	114/10/8	
8	化工館 Department of Chemical Engineering	4F	<1	114/10/8	
9	化學館 Department of Chemistry	1F 交誼廳 Common area	<1	114/10/8	
10	工程一館工工系 Engineering Building I : Department of Industrial Engineering and Engineering Management	2F	<1	114/10/8	
11	清華幼稚園 Tsing Hua Kindergarten	東院10號 East Yuan Faculty Residences No.10 辦公室	<1	114/10/8	
12	文學館 Museum of Literature	B1	<1	114/10/8	
13	清齋 (Dorm Tsing)	B棟 (Building B) 9樓 (9th floor)	<1	114/10/8	
14	明齋 (Dorm Ming)	1樓浴室 (1st floor bathroom)	<1	114/10/8	
15	學齋 (Dorm Shiu)	A棟 (Building A) 7樓 (7th floor)	<1	114/10/8	
16	清齋 (Dorm Tsing)	A棟 (Building A) 3樓 (3rd floor)	<1	114/10/8	
17	清齋 (Dorm Tsing)	DE棟 (Building DE) 8樓 (8th floor)	<1	114/10/8	
18	儒齋 (Dorm Ru)	C棟 (Building C) 6樓 (6th floor)	<1	114/10/8	
19	儒齋 (Dorm Ru)	A棟 (Building A) 1樓 (1st floor)	<1	114/10/8	
20	禮齋 (Dorm Li)	2樓 (West side of the 2nd floor)	<1	114/10/8	
21	文齋 (Dorm Wen)	2樓 202 (Room 202, 2nd Floor)	<1	114/10/8	
	以下空白				

註1. 飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

編號 No.	單位名稱 The name of the organization	地點 Location of installation	大腸桿菌群 Coliform	採樣日期 Collection Date	檢測結果 Test results
二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City					
1	綜合教學大樓-5F-前端茶水間 General Education Building-5F-the front tea room		<1	114/10/8	符合規定 in compliance with regulations
2	學生第一活動中心-2F-洗手間旁 Student Activity Center 1-2F-beside toilet		<1	114/10/8	
3	體健大樓-3F-廁所旁 Health and Physical Education Building-3F-beside toilet		<1	114/10/8	
4	推廣教育大樓-2F-後端洗手間旁 Extended Education Building-2F-beside back toilet		<1	114/10/8	
5	樹德樓-3F-312室旁 Shu Te Dorm-3F-beside 312 Room		<1	114/10/8	
	以下空白				

註1.飲用水水質標準 Note 1. Drinking water quality standards

大腸桿菌群 Coliform : 6 (CFU/100mL)

